Lee County Board Of County Commissioners Agenda Item Summary

Blue Sheet No. 20030616

1. <u>REQUESTED MOTION</u>:

٩.

ACTION REQUESTED: Approve Bid Waiver #W-030541 to waive the formal quotation procedure and allow the Lee County Division of Public Safety to proceed with the remount/modular refurbishment of four (4) of its ambulances at a cost of \$372,460.00; and the modular refurbishment of three (3) of its ambulances at a cost of \$119,994.00 – total cost: \$492,454.00. The work will be performed by American LaFrance MedicMaster. A waiver has been requested to this vendor, the original manufacturer of these ambulances, in order to keep the 20-year ambulance modular warranty (provided at original purchase) valid. Also approve the expenditure of a not-to-exceed amount of \$75,000.00 to cover any unforeseen damage that may be uncovered during the course of these procedures.

<u>WHY ACTION IS NECESSARY</u>: According to Section 9.4.1 of the Lee County Purchasing & Payment Procedures Manual, approved by the Board on 7/9/02, purchases over \$50,000.00 must be approved by the Board.

<u>WHAT ACTION ACCOMPLISHES</u>: Allows Public Safety to maintain its ambulance fleet to the prescribed standards; thus maintaining its response time reliability and service to the public.

2. <u>DEPARTMENTAL CATEGORY</u> : COMMISSION DISTRICT #			ATA			3. <u>MEETING DATE</u> : 06 - 10 - 2003	
4. <u>AGENDA</u>	:		REQUIREMENT/PURPOSE: Specify)			6. <u>REQUESTOR OF INFORMATION</u> :	
CON	SENT		STATUTE			A. COMMISSIONER	
X ADM	IINISTRATIV	E	ORDI	NANCE		B. DEPARTMENT	
APP	EALS	X	ADMI CODE		AC-4-1	C. DIVISION	Public Safety
PUB			OTHE	R		BY: _John W	ilson, Director
	LK ON <u>E REQUIRED</u>	:					
8. <u>MANAGE</u>	MENT RECO	MMENDAT		COMMENI	DED APPI	ROVAL:	
Α	B	С	D	E		F	G
Department	Purchasing	Human	Other	County		Budget Services	County Manager
Director	or Contracts	Resources		Attorney		ann shelo's	
Wall 102	Jan Shiehan			Dura	OA		GC
15/22/02	1 5. xc. 03			Jules	elem us		15,25.03
10. <u>COMMI</u>	SSION ACTIO	<u>N</u> :				RECEIVED	Y
U				Rec	by CoAtty		MIN. GW
		_ APPROV DENIED	LD		5/17/0	5/27-	40
		DERIED	ED	Tim		AD:	IIN. JA
		OTHER			arded To:	5/29-	TO: XS/

--BACKGROUND CONTINUED FROM PAGE ONE--

On April 28, 2003, the Division of Purchasing received a request from the Lee County Division of Public Safety to waive the formal quotation procedure and to proceed with the remount/modular refurbishment of four (4) of its ambulances at a cost of \$372,460.00; and the modular refurbishment of three (3) of its ambulances at a cost of \$119,994.00 – total cost: \$492,454.00. The work will be performed by American LaFrance MedicMaster. A waiver has been requested to this vendor, the original manufacturer of these ambulances, in order to keep the 20-year ambulance modular warranty (provided at original purchase) valid – please see below and attachments. It was also requested by Public Safety that Board approval be obtained for the expenditure of a not-to-exceed amount of \$75,000.00 to cover any unforescen damage that may be uncovered during the course of these procedures.

According to Section 9.4.1 of the Lee County Purchasing & Payment Procedures Manual, approved by the Board on 7/9/02, purchases over \$50,000.00 must be approved by the Board.

This request for a bid waiver is predicated on, and justified by, the following factors (which have been researched and verified by both Public Safety and Purchasing):

*Modular Warranty. The 20-year ambulance modular warranty (provided at original purchase) will be continued if American LaFrance MedicMaster does the work. If these procedures are performed by any other party, this warranty would be voided.

*Other Warranties. An ambulance is a complicated vehicle; and, as such, comes with a variety of warranties on its systems and components - i.e., electrical, mechanical, paint, etc. Having the work performed by American LaFrance MedicMaster assures that all warranties will continue and not be voided.

*Vendor Performance. Public Safety has a number of MedicMaster ambulances in its fleet; and has been pleased with the vendor's performance and service over the past several years. Consequently, the vendor is familiar with Public Safety's specifications and requirements for its ambulances; knowledge that should make this process move ahead quickly and with minimum delay.

*Chassis Availability. American LaFrance MedicMaster is a Freightliner dealer; and traditionally sells Public Safety the Freightliner chassis for the ambulances at "dealer net". Three out of the four chassis to be used under this project are being sold to Lee County below "dealer net"; with the fourth at "dealer net". Result: Chassis costs are kept to a minimum; bringing down the overall cost of the project.

Funding is available: KF5260100100.506430 General Fund – Independent Department, Public Safety Division, Emergency Response Vehicles, Vehicles and Rolling Stock

ATTACHMENTS:

- (1) Division's Request for a Bid Waiver
- (2) Confirmations of 20-Year Warranty Terms/Chassis Pricing
- (3) American LaFrance MedicMaster's Quotation/Specifications for the Ambulance Refurbishment/Modular Rechassis

MEMORANDUM FROM THE DIVISION OF PURCHASING

DATE: MAY 20, 2003

TO: <u>MARILYN RAWLINGS</u> FLEET MANAGER FROM: JANET SHEEHAN, CPPB PURCHASING DIRECTOR


RE: BLUE SHEET # 20030616

PROJECT:	Ambulance Refurbishment/Modular Rechassis		1
TYPE:	Bid Waiver		• •
		•	
AWARDED	<u>TO</u> : American LaFrance MedicMaster		рэ. 19
		L i	£
		• • • • •	

<u>Attn. Ms. Rawlings</u> – When you have finished your review of this package, please forward it to John Wilson, Public Safety.

<u>Attn. Mr. Wilson</u> - When you have finished your review of this package, please forward it to Kristie Kroslack in the County Attorney's Office.

If there are any questions or concerns with this package, please contact Bob Franceschini at 689-7385.



ATTACHMENT#1

03 APR 29 PH 1:2

Division of

EMS MEMO

Public Safety

To: Janet Sheehan, Purchasing Director

From: Chief Chris Hansen, EMS Manager

Subject: Ambulance Refurbishment / Modular Rechassis

Date: April 28, 2003

The purpose of this memo is to respectfully request assistance to secure BoCC approval to proceed with previously budgeted / approved ambulance chassis remounts and refurbishments. EMS recommends using MEDIC MASTER, the original ambulance manufacturer for the following reasons:

- The 20-year ambulance modular warranty (provided at original purchase) will be continued and not voided.
- Additional warranties continue and are not voided (i.e., electrical, mechanical and paint)
- Vendor familiarity with Lee County specifications.
- Satisfactory performance of vendor to date.
- MEDIC MASTER has a model year(s) chassis overstock. This will avoid unnecessary delays and provide Lee County with pricing incentives.

Lee County EMS requests that the BoCC to approve MEDIC MASTER as our sole source ambulance remount / refurbishing vendor with a not to exceed amount of \$492,454. The following table and enclosed specifications detail the amount and types of work we are requesting.

4 - Ambulance Remount / Modular Refurb.	\$372,460
3 – Ambulance Modular Refurbishment	\$119,994

The budget line item / account string for this purchase would be KF5260100100.506430 = General Fund - Independent Department, Public Safety Division, Emergency Response Vehicles, Vehicles and Rolling Stock. Janet Sheehan, Purchasing Director Page 2 April 28, 2003

.

This purchasing process will allow Lee County maintain its ambulance fleet to the prescribed standards, helping to maintain our response time reliability and service to the public.

....

Michael Bridges, Public Safety Deputy Director Approved:

Patti Hojnacki, Fiscal Officer CC: Marilyn Rawlings, Fleet Manager

Division of

MEMO

Public Safety

To:Chris HansenFrom:Lt. Jay BridenthalSubject:Re-chassis / Refurbishment of AmbulancesDate:May 1, 2003

As you are aware I have spent many hours over the last year collecting the necessary information in reference to the re-chassis and/or refurbishment of several LCEMS ambulances. This information has also been acquired in the almost daily contacts with ambulance manufacturers that I have had in the past 3 ½ years.

Modular Warranty: Almost without exception, any manufacturer will guarantee or continue the original warranty, if you elect to have the original manufacturer provide the re-chassis / refurb program. In addition, if you allow another manufacturer to alter the original components, the original warranty will be voided.

I have yet to speak with any manufacturer that will warranty or guarantee any component of another manufacturers product. This includes three manufacturers that LCEMS currently utilizes their products.

Workmanship Warranty: Once again, any manufacturer will only warranty the actual work that they perform, not parts or components of another manufacturer. The normal workmanship warranty period is 12 months.

Robert Franceschini - refurbprop.wpd

[Name of Recipient(s)] Page 2 May 9, 2003

Familiarity: Just as you would not take your Toyota to a Ford dealer for body or mechanical work, the same holds true in the commercial vehicle market.

Based on the above and many other variables, I strongly suggest that we enter into an agreement with MedicMaster for the re-chassis / refurb of 7 MAV ambulances that were originally manufactured by MedicMaster.

In the event that we elect to re-chassis the three Ford AEV ambulances in the future, AEV would be the front runner for this program. However, the past performance, satisfaction and reliability would have to be addressed.

cc: Robert Franceschini





03 MAY 19 AM 9: 15

May 17, 2003

American LaFrance MedicMaster 3705 St. Johns Parkway Sanford, Florida 32771 phone: (800) 292-2376 fax: (800) 642-7895 email: medicmst@bellsouth.net

Mr. Bob Franceschini Lee County Purchasing Department 3434 Hancock Bridge Parkway North Fort Myers, Florida 33903

RE: Sole Source Justification

(A) Modular Body Structural Warranty:

Your modular ambulance body has a 20 years warranty. This body is custom designed with special extrusions that are available only to American LaFrance Medicmaster (ALFMM). The methods of constructions are familiar only to ALFMM. The failure to follow each and every method, and procedure will jeopardize the warranty. This is especially true when transferring the body to a new chassis.

The "Exclusions from Warranty" section "G" of your warranty document states:

Remount by anyone other than the Manufacturer or its authorized remount facility.

(B) Ambulance Electrical system:

The electrical system that operates the emergency warning systems, heating and air conditioning, life support systems, interior lighting, exterior lighting, and DOT lighting systems are custom designed by ALFMM. No other company has any knowledge about this system. When you remount an ambulance body on a new chassis this system must be removed, and then interfaced into the new chassis. This is more difficult due to the differences in the original and the new chassis that your modular body is being remounted on. Only the original manufacturer is qualified to do this.



American LaFrance MedicMaster 3705 St. Johns Parkway Sanford, Florida 32771 phone: (800) 292-2376 fax: (800) 642-7895 email: medicmst@bellsouth.net

(C) Heating and Air Conditioning System:

A condition of this contract is to replace the heating and air conditioning system in the patient compartment. The contract requires a system identical to the systems installed in your new ALFMM ambulances. This system provides a significant increase in performance. In order to accomplish this every system "electrical, heating, air conditioning, and the modular body" is effected. In addition to the systems mentioned above the forward bulkhead center cabinets will be replaced also. Only ALFMM is qualified to do these modifications, and insure the best results.

I hope this information is lends clarity to this project. Please let me know what I can do if further information is needed.

Respectfully, Bob June American LaFrance Medicmaster

20 YEAR LIMITED WARRANTY

Modular Body Structure

AERO PRODUCTS CORPORATION warrants to the original owner subject to the provisions, limitations, and conditions set forth in this warranty that the aluminum modular body is structurally sound and free of joint separation, cracks, and all other structural defects of both materials and workmanship and further warrants that it will maintain its structural integrity as long as said body is owned and maintained by the original purchaser.

The sole responsibility of AMERICAN LAFRANCE MEDICMASTER under this warranty shall be to replace or repair any defective part at its option. AMERICAN LAFRANCE MEDICMASTER shall not be liable for any consequential damages, whatsoever. The warranty period shall begin on the date the vehicle is delivered to the Owner.

Written notice of a claim under this warranty shall be given to AMERICAN LAFRANCE MEDICMASTER within a reasonable time after any defect is discovered or should have been discovered.

Exclusions from Warranty.

- A. Any parts or products becoming defective as the result of misuse, negligence, accident or other casualty and/or Owner's failure to provide normal maintenance.
- B. Paint finish, hardware, trims, moldings, windows, interior cabinets, and other appointments or accessories.
- C. Owner's improper installation of components, repairs, or alterations.
- D. Operation in a manner contrary to normal, safe, legal or established practices.
- E. Any part not manufactured by AMERICAN LAFRANCE MEDICMASTER along with parts needing replacement due to normal wear.
- F. Should replacement or repair become necessary under the terms of this warranty the extent of that replacement or repair shall be determined solely by AMERICAN LAFRANCE MEDICMASTER. Transportation expenses to or from a repair facility, meals, or lodging expenses shall be that of the purchaser and is not an item covered by this warranty.
- G. Remount by anyone other than the Manufacturer or its authorized remount facility.

Conditions:

- A. This warranty is valid only in the United States of America.
- B. AMERICAN LAFRANCE MEDICMASTER does not authorize any person to make any representations, obligation or warranty on its behalf other than that stated in this warranty.
- C. Replacement or repair of any part or component under this warranty by AMERICAN LAFRANCE MEDICMASTER shall not extend this warranty beyond the original period.
- D. AMERICAN LAFRANCE MEDICMASTER does not warrant the workmanship of owner's negotiated installers and will not bear any cost due to incorrect or faulty installation or loss of part or component.
- E AMERICAN LAFRANCE MEDICMASTER will not be liable for consequential or Incidental damages of any kind whatsoever in connection with the sale and use of this vehicle.

IT IS EXPRESSLY UNDERSTOOD THAT THIS WARRANTY IS PROVIDED IN PLACE OF ANY IMPLIED WARRANTY OF MERCHANTABILITY AND ANY IMPLIED WARRANTY OF FITNESS, WHICH ARE HEARBY EXCLUDED. YOUR RIGHT TO REPAIR OR REPLACEMENT OF DEFECTIVE PARTS ON THE TERMS EXPRESSLY SET FORTH HEREIN IS YOUR EXCLUSIVE REMEDY, AND THE MANUFACTURER SHALL NOT BE LIABLE FOR DAMAAGES, WHETHER ORDINARY, INCIDENTAL, OR CONSEQUENTIAL UNDER THIS WARRANTY. ANY REMEDY OF CONSEQUENTIAL DAMAGES, INCLUDING ECONOMIC LOSS, AND ANY REMEDY OF INCIDENTAL DAMAGES ARE HEREBY EXCLUDED. THIS WARRANTY GIVES YOU SPECIFIC LEGAL RIGHTS, AND YOU MAY HAVE OTHER RIGHTS WHICH VARY FROM STATE TO STATE.

For prior approval of all warranty work call 800-292-2376



03 MAY 19 AM 9: 15

American LaFrance MedicMaster 3705 St. Johns Parkway Sanford, Florida 32771 phone: (800) 292-2376 fax: (800) 642-7895 email: medicmst@bellsouth.net

May 17, 2003

Mr. Bob Franceschini Lee County Purchasing Department 3434 Hancock Bridge Parkway North Fort Myers, Florida 33903

RE: Chassis Sole Source Justification

American LaFrance Medicmaster is a Freightliner Dealer. The chassis provided on a new unit are sold to you are what is called "dealer net". The chassis offered in this proposal are all offered below "dealer net". I have provided Lt. Jay Bridenthal detailed Freightliner specifications of each chassis. If there is any question concerning pricing of the chassis I would encourage you to check these with a Freightliner dealer.

Remount Proposal # 1 & 2:

These chassis are 2002 chassis that are on hand at the Sanford Plant: These chassis were ordered in January 2002. The customer decided to change to the new Freightliner "M-2" and these became surplus. These are being offered below "dealer net" at 17 month old pricing.

Remount Proposal # 3:

This chassis is a 2001 chassis that is on hand at the Sanford Plant. This chassis was lost in the system at Orlando Freightliner for over a year. We obtained from them. The cost of this chassis is \$49,000.00, and we have offered it for 35,940.00.

Remount Proposal # 4:

The chassis will be a 2004 Model. It is being offered at "dealer net" price of \$46,761.00. This chassis will have to be ordered.



American LaFrance MedicMaster 3705 St. Johns Parkway Sanford, Florida 32771 phone: (800) 292-2376 fax: (800) 642-7895 email: medicmst@bellsouth.net

. .

The chassis offered in proposals # 1, 2, and 3 are new, and never been titled. There warranties will start when they are delivered.

I hope this information is lends clarity to this project. Please let me know what I can do if further information is needed.

Respectfully, Bob Ivey American LaFrance Medicmaster





April 25, 2003

Jay Bridenthal Lee County Emergency Medical Service 14752 Six Miles Cypress Parkway Fort Myers, Florida 33912 American LaFrance MedicMaster 3705 St, Johns Parkway Santord, Florida 32771 phone: (800) 292-2376 lax: (800) 642-7895 email; medicmst@bellsouth.net

RE: Remount/Refurbish Proposal

Dear Jay:

I thank you for the opportunity to make the following proposal to remount, and refurbish four MedicMaster Emergency Medical Vehicles. This will extend the useful service life of these vehicles for many years. All the units involved in this project are identical in age and design. The scope of the project in regards to items that are worn out or damaged is the same on all units. There are minor differences that will have to be dealt with in each unit. Once the units are received minor problems will be absorbed at no additional cost. If a major problem is found we will have to evaluate it as to cost. Generally this usually is wood rot found after the flooring is pulled out. The improvements to be made are the same on all units.

By allowing American LaFrance MedicMaster to transfer the modular patient compartments to a new chassis will insure the 20-year structural warranty will stay inforce. Transferring a patient compartment module to a new chassis by an unqualified company would terminate the structural warranty. A twelve-month warranty will be provided on work performed remounting, and refurbishing each unit.

I have made three separate proposals. The difference is the Freightliner Chassis in each proposal. I have three new chassis that have never been used. Two 2002 FL-60's were ordered, and after receipt the customer decided to use the new "M2" chassis. The other is a 2001 FL-60 that Orlando Freightliner lost in their system for over a year. The three chassis have a collective savings of \$21,000.00 below cost. The fourth chassis is a new 2003 chassis. I have stopped the sale of the three chassis to other agencies. I will need a commitment on them to prevent their sale.

Proposal # 1: Remounts # 1 & 2 - \$93,957.00 each Proposal # 2: Remount # 3 - \$87,620.00 each Proposal # 3: Remount # 4 - \$96,926.90 each



.

American LaFrance MedicMaster 3705 St. Johns Parkway Sanford, Florida 32771 phone: (800) 292-2376 fax: (800) 642-7895 email: medicmst@bellsouth.net

I have provided a detailed specification for each proposal, and a chassis specification. Please let me know what I can do to assist further.

Döb

Bob Ivey American LaFrance MedicMaster

L ...

1

.

	АВ	С
1	CUSTOMER INFORMATION	
2	±	
3		
4	Remounts #1 & 2	
5		
6	Work Order Number:	
7		
8	Date:	
9	2-18-2003	
10		
11		
12		
13		
14	Primary Contact Person:	
15	Jay Bridenthal - Supervisor	
16	(941) 335-1623 - Phone	
17	(941) 930-8618 - Pager	
18	(941) 335-1638 - Fax	
19	bridenja@leegov.com	
20	rawlinml@leegov.com	
21	Contact Person:	
22	Chris Hansen - Program Manager	
23	Richard (Rocco) Cranford - Operations Manager	
24	Telephone:	
25	(941) 335-1600 - Main Number	
26	(941) 335-1604 - Chris	
27	(941) 335-1636 - Rocco	
	(941) 338-3239 Danny Brashear & Randy Feinstein & Mark	
28	Clugston - Fleet Management	
29	(239) 338-3234 - Shop Fax	
30	brashedr@leegov.com	
31	Fax Number:	
32	(941) 335-1638	
33		
34		
35		
36		
37	Plant Contact:	
38	Bob ivey	
39		
40	Delivery Point (F.O.B.):	
41	Fort Myers, florida	
42		1
43	Transportation:	
44	Fort Myers to Sanford	400.00
45	Sanford to Fort Myers	400.00
46		
47	*	
48	CAB & CHASSIS	
49	*	

	A	В	С
50			
51			
52		Chassis Manufacturer:	42,567.00
53		Freightliner	
54		Chassis Model:	
55		FL-60 (2) door Cab	
56		Chassis Model Year:	
57		2002	
58		VIN#:	
59		<u>V11177.</u>	
60			
61		Engine:	
62		Cummins ISB 260HP	
63		Transmission:	
64		Allison 2400 series "T" Shifter 5 speed with park pawl	
65		Brakes:	
66		Hydraulic	
67		Tyoraunc	
<u> </u>			
68		*	
69		CHASSIS PREPARATION	
70 71		CHASSIS PREPARATION	
72		Demount modules hady 24 hours	1,200.00
73 74		Demount modular body - 24 hours Remount modular body - 40 hours	2,000.00
		Disconnect Electrical, AC, Heater, ETC - 16 hours	800.00
75		Disconnect Electrical, AC, neater, ETC - To hours	000.00
76 77		Tow Maaka Or Evan	0.00
78		Tow Hooks Or Eyes: Rear: None	0.00
79		Redi. None	
80		Fuel Tenk Cover/Entry Sten	
81		Fuel Tank Cover/Entry Step: Move existing cover	200.00
-01		Fuel tank cover with step on passengers side100" diamond	200.00
82		plate aluminum.	
		•	
83 84		45 gallon fuel tank hours - (4)	
85 86		Battery Storage/Entry Step:	
87		Install new battery box - materials	950.00
88		Hours - (6)	300.00
_00 89		Slideout battery tray with step on drivers side.	300.00
90		Material: .100" diamond plate aluminum.	
90		material 100 ulanona plate diuminum.	
91		Air Dida Suepaneian	100.00
		Air Ride Suspension:	100.00
93		Interface with existing system	
94		Exhaust System	400.00
95		Exhaust System:	400.00
		Exit at a 45 dagree and a farmer of the stread ide where we	
96		Exit at a 45 degree angle forward of the streetside wheel well	
97			

.

Lee County EMS Rechassis

	AB	С
98	Cab And Module Passage-Way:	400.00
99	Walk thru with no door	55.00
100	hours - (8)	
101		
102	*	
103	PAINT, LETTERING & STRIPING	
104	· • •	
105		
106	Primary Paint:	
107	Brand: PPG	7,500.00
108	Color: White	
109	Paint Number: DHUS-2185	
110	Location: Total unit	
111	Bead Blast: Module	1,100.00
112	Zolatone Compartments: Gray	500.00
113	R & R modular body components	2,000.00
114	Paint & Supplies:	1,100.00
115		1,100.00
116	Reflective Striping & Graphics:	800.00
117	See pictures in file	150.00
118		100.00
119	Undercoating:	50.00
120	Front wheel wells	30.00
121		00.00
122	*	
123	<< CAB AREA >>	
124	*	
125		
126	Rocker Switch Panel;	100.00
127	Transfer	
128		
129	Cab Console:	500.00
130	Install new console - Design TBA	300.00
131	Material	150.00
132		
133	Door Open Warning Panel:	50.00
134	Transfer	2
135		
136	Voltmeter:	50.00
137	New Gauge	50.00
138	-	
139	Ammeter:	50.00
140	New Gauge	75.00
141	-	
142	Dash Protective Plate:	100.00
143	Install .100" smooth aluminum plate "DA" finished	10.00
144		
145	Power Supply:	50.00
146	Install cigar lighter receptacle in center console	10.00
147		

,

?, t

- -

	A	В	С
148		*	
149		<< 12v DC ELECTRICAL SYSTEM >>	
150		*	
151			
152		Electrical:	
153		Disconnect cab harness & reinstall	2,000.00
154		General electrical hours	5,000.00
155			
156		Batteries:	0.00
157		Four (4) GP31's in slideout tray left step.	
158			
159		Battery Switching:	0.00
160		Paddle on/off - Left of drivers seat	
161			
162		Battery "ON" indicator:	0.00
163		Green indicator OEM installed on dash	
164			
165		<u>Alternator:</u>	0.00
166		320A OEM installed	
167			
168		Auto-Throttle:	
169		Interface electronic engine	100.00
170			
171			
172			
173		120 Volt System	
174 175		Charaltan # 4.	
176		<u>Shoreline # 1:</u> Kussmaul 20A Super Auto-Eject	150.00
177			363.00
178		Power Source For: Battery charger & interior outlets	
179		Positions TBA due to tail light package	
180	"	r ositons r bA due to tail light package	
181		Shoreline # 2;	450.00
182		Kussmaul 20A Super Auto-Eject	150.00
183		Power Source For: Roof top air conditioner	363.00
184	•		
185	1	<u>Circuit Breaker Panel:</u>	250.00
186		Square "D" panel with (2) 20A GFI circuit breakers	250.00
187		a stand a band with (2) 207 OF1 CICUIL DIGARCIS	200.00
188	1	Power Strip 120V:	100.00
189	-	Six (6) outlets	100.00
190		Compartment # 7	60.00
· · · ·			
191	i	Location: vertical right on wall # 3 - flush with top cmpt. Panel	
192	_		
193		*	
194		<< ICC & DOT LIGHTING & REQUIRED DEVICES >>	
195		*	
196			

- -

<u> </u>	A	В	C
197		Clearance and Marker Lights:	100.00
198		Weldon LED's with S/S guards	80.00
199		Standard ICC/DOT body reflectors.	
200		Back Up Alarm:	
201		DOT approved back up alarm.	50.00
202		Tail Light Housing:	
203		Interface with new chassis	100.00
204		Brake/Tail Lights:	
		Whelen 900 Series Red lens # 90R00XRR with flange - (2)	
205		each	560.00
206		Turn Signals:	
		Whelen 900 Series Amber Guide Arrows # 90A00TAR with	
207		flange - (2) each	464.00
208			
209			
210		*	
211		<< K.K.K. SAFETY PLACARDS >>	
212		*	
213			
214		Product Logo:	
215		Two (2) Medicmaster™ name plates.	
216		Seat Belt Warning Sign:	
217		1. Cab.	15.00
218		No Smoking/Oxygen Sign:	
219		1. Cab.	15.00
220		Star of Life Certification:	
221		As required.	
222		Payload Weight Certification:	
223		As required.	
224		FMVSS Label:	
225		As required.	
226		AMD Label:	
227		As required.	
228			
229			
230		*	
231		<< AUDIBLE EMERGENCY WARNING DEVICES >>	
232		*	
233			
234		Electronic Siren:	150.00
235		Remove & reinstall	
236			
237		Speakers:	
238		R & R both speakers	150.00
239			
240		Air Homs:	
241		Install button to activate horns - upper center of dash plate	150.00
242		OEM floor switch	
243		· _	
244	L	*	

ير د ب

.

	Α	Г В	c
245		< VISUAL WARNING DEVICES >>	~
246		*	
247			
248		Front Light Bar:	400.00
249		Whelen Model 5000KKF LED	1,550.00
250		Lens Configuration: RRRCRRR	1,000.00
251			
252			
253		Rear Light Bar:	400.00
254		Whelen Model 5000KKF LED	1,400.00
255		Lens Configuration: RRRCACRRR	1,400.00
256		Switch As: Rear Light Bar	
257			
258		<u>Grill:</u>	100.00
259		Whelen 900 strobe split red/clear with flange	167.00
260		Curbside upper corners of grill.	
261		Primary/Secondary	
262		· · · · · · · · · · · · · · · · · · ·	
263		<u>Grille:</u>	100.00
264		Whelen 900 strobe split red/clear with flange	167.00
265		Streetside upper corners of grill.	107.00
266		Primary/Secondary	
267		·········	
268		Forward Intersector:	100.00
269		Whelen 700 strobe split red/clear with flange	157.00
270		Streetside engine cowling	
271		Primary/Secondary	
272			
273		Forward Intersector:	100.00
274		Whelen 700 strobe split red/clear with flange	157.00
275		Curbside engine cowling	
276		Primary/Secondary	
277			
278		Rear Intersector:	100.00
279		Whelen 700 strobe - red lens with flange	147.00
280		Center above rear wheel wells	
281			
282		Rear Intersector:	100.00
283		Whelen 700 strobe - red lens with flange	147.00
284		Center above rear wheel wells	
285			
286		Rear Modular Body:	325.00
287		Whelen 900 LED amber lens with flange	100.00
288		Streetside - midlevel - position upper window level	
289		Primary/Secondary	
290			
291		Rear Modular Body:	325.00
292		Whelen 900 LED amber lens with flange	100.00
293		Curbside - midlevel - position upper window level	
294		Primary/Secondary	

.'

s. ;

...

	<u>A</u> B	С
295		
296	LED Flasher:	100.00
297	Weldon LED flasher	110.00
298	,	
299	Strobe Power Supply:	200.00
300	Whelen UPS 690	473.00
301		
302	Spotlight:	100.00
I -	Collins Model #CL-12 <> hardwire <> aluminum ho	olster right
303	side of center console	160.00
304		
305	Block Heater:	0.00
306	None	0.00
307		
308	Interior 120 Receptacles:	50.00
309	Check for proper operation - R & R if necessary	50.00
310	check of proper operation. It at the necessary	
311	Rear Step Bumper:	100.00
312	Install new bumper	
313	Dock Bumper: Yes	750.00
515	Reflective Stripe: Red/White on rear facing face of	50.00
314	section	•
315	Section	25.00
316		
	Compartment Lighting:	0.00
317	Check all lights for proper operation	
318	Market Street Street	
319	Modular Body Doors:	350.00
220	Check each door for proper timing, & worn out item	IS.
320	Replace or repair as necessary	
321		
322		
323		
324	PATIENT COMPARTMENT	
325		
326		
327	Air Conditioner/Heat Unit:	
	Replace air conditioning cabinet on upper forward b	
	Install top hinged door, (2) gas struts, return air ven	•
328	new cushion under cabinet	760.00
	Install new Hoseline Model ACHU1128R air condition	oning
329	evaparator and accessories	2,600.00
180 331		
	Roof AC/Heat Unit:	1,200.00
332	Duothrem Penguin	645.00
333	Distribution Box - polar white	90.00
334	Electronic Kit	110.00
335	Thermostat - action aera wall	1.0.00
202	Electric heat strip 5,600 BTU	
336		

.′

.

1 j 1. 1

	A	В	С
		Condensation drain lines shall terminate in a catch basin	
_338		under modular body - Quarter turn drain valve to empty pan	350.00
339		Power AC with shoreline	
		Install roof pan to prevent condensation runoff when unit is	
340		parked on a 10 degree angle	
		Deflector Shield188" with 6"H X 18"W openiings - (1)	
341		forward & (2) each side	550.00
		Angle forward & rear vertical sides of openings so they align	
342		with the front slant of the shield - both side openings	100.00
343		Clearance Sign: TBA	
344		-	
345		Floor:	1,500.00
346		Install Lonseal II # 421 Mica flooring	350.00
347		v	
348		Upholstery:	1,000.00
349		Replace all uphoistery	400.00
350			
351		Interior Repairs:	
352		Repair latch on squad bench	50.00
353		Replace (2) Jedcos on squad bench	50.00
354		Replace all interior gas struts	50.00
355		Struts	150.00
356		Replace Southco latch at forward end of squad bench	25.00
357			
358		Fans 12V Non-Oscillating:	
359		Two (2) Bergstrom Model #756360 fans.	100.00
360		1. Streetside wall at rear cabinet	100.00
361		2. Wall left of the AC access door	100.00
362			
363			
364			
365		Total	93,957.00

5. ×

·····		
<u> </u>	A B	C
1	CUSTOMER INFORMATION	
2	*	
3		
4	Remount # 3	
5		
6		
7	Work Order Number:	
8		
9	Date:	
10	12-29-2002	
11	2-5-2003	
12		
13		
14		
15	Primary Contact Person:	
16	Jay Bridenthal - Supervisor	
17	(941) 335-1623 - Phone	
18	(941) 930-8618 - Pager	
19	(941) 335-1638 - Fax	
20	bridenja@leegov.com	
21	rawlinml@leegov.com	
22	Contact Person:	
23	Chris Hansen - Program Manager	
24	Richard (Rocco) Cranford - Operations Manager	
25	Telephone:	
26	(941) 335-1600 - Main Number	
27	(941) 335-1604 - Chris	
28	(941) 335-1636 - Rocco	
	(941) 338-3239 Danny Brashear & Randy Feinstein & Mark	ζ
29	Clugston - Fleet Management	
30	(239) 338-3234 - Shop Fax	
31	brashedr@leegov.com	
32	Fax Number:	
33	(941) 335-1638	
34		
35		
36		
37		
38	<u>Plant Contact:</u>	
39	Bob Ivey	
40	-	
41	Delivery Point (F.O.B.);	
42	Fort Myers, florida	
43		
44	Transportation:	
45	Fort Myers to Sanford	400.00
46	Sanford to Fort Myers	400.00
47	· · · -	100.00
48	*	
	CAB & CHASSIS	
49	CAB & CHASSIS	

,

٩,

۴.

.

	A	В	С
50	<u> </u>	*	
51			
52			
53		Chassis Manufacturer:	35,940.00
54		Freightliner	
55		Chassis Model:	
56		FL-60 (2) door Cab	
57		Chassis Model Year:	
58		2001	
		2001 VIN#:	
59 60			
		Engine	
61		Engine: Cummins ISC 315HP	
62			
63		Transmission: Allison MD3060P	
64			
65	1	Brakes:	
66		Hydraulic	
67		*	
68	ļ		
69	ł	CHASSIS PREPARATION	
70	Į	-	
71		Demonstrandular hade 24 hours	1,200.00
72		Demount modular body - 24 hours	2,000.00
73]	Remount modular body - 40 hours	800.00
74	ļ	Disconnect Electrical, AC, Heater, ETC - 16 hours	800.00
75	ļ		0.00
76		Tow Hooks Or Eyes:	0.00
77		Rear: None	
78]		
79	l	Fuel Tank Cover/Entry Step:	200.00
80	ļ	Move existing cover	200.00
		Fuel tank cover with step on passengers side100" diamond	
81	l	plate aluminum.	
82	1	45 gallon fuel tank	
83	1	hours - (4)	
84	Į		
85	4	Battery Storage/Entry Step:	050.00
86	ł	Install new battery box - materials	950.00
87	}	Hours - (6)	300.00
88	1	Slideout battery tray with step on drivers side.	
89	Į	Material: .100" diamond plate aluminum.	
90	1		400.00
91	1	Air Ride Suspension:	100.00
92	}	Interface with existing system	
93	1		100 10
94]	Exhaust System:	400.00
•			
95	1	Exit at a 45 degree angle forward of the streetside wheel well	
96	ł		
	L	Cab And Module Passage-Way:	400.00

.'

ť

	A	В	
98		Walk thru with no door	55.00
99		hours - (8)	
100		fiours - (0)	
		Air System PING Tank:	40.00
101		Install OEM System	250.00
102		Instan OEM System	200.00
103			
104 105		· *	
105		PAINT, LETTERING & STRIPING	
100		, FAINT, ELT ENNO & OTNE MO	
107			
108		Drimony Paint:	
		Primary Paint: Brand: PPG	7,500.00
110	``	Color: White	
111 112		Paint Number: DHUS-2185	
112		Location: Total unit	
113	ł	Bead Blast: Module	1,100.00
		Zolatone Compartments: Gray	500.00
115		R & R modular body components	2,000.00
<u>116</u> 117	l	Paint & Supplies	1,100.00
	-	Paint & Supplies	1,100.00
118		Reflective Striping & Graphics:	800.00
119	ł	See pictures in file	150.00
120 121	1	See pictures in me	100.00
121	4	<u>Undercoating:</u>	50.00
122	4	Front wheel wells	30.00
123			00.00
124	}	*	
125	{	<< CAB AREA >>	
120	{	*	
127	4		
120	ł	Rocker Switch Panel:	100.00
130	1	Transfer	
131	{		
132	1	Cab Console:	500.00
132	1	Install new console - Design TBA	300.00 '
134	1	Material	150.00
135	4	-	
136	1	Door Open Warning Panel:	50.00
137	1	Transfer	
138	1		
139	ł	Voltmeter:	50.00
140	1	New Gauge	50.00
141	1		
142	ł	Ammeter:	50.00
143	1	New Gauge	75.00
144	1		
145	1	Dash Protective Plate:	100.00
146	1	Install .100" smooth aluminum plate "DA" finished	10.00
147	1		
	1		

.

÷

÷

	A	B	С
148		Power Supply:	50.00
149	1	Install cigar lighter receptacle in center console	10.00
150	1		
151		*	
152		<< 12v DC ELECTRICAL SYSTEM >>	
153	-	*	
154			
155		Electrical:	
156		Disconnect cab harness & reinstall	2,000.00
157	1	General electrical hours	5,000.00
158			
159	1	Batteries:	0.00
160		Four (4) GP31's in slideout tray left step.	
161			
162		Battery Switching:	0.00
163	1	Paddle on/off - Left of drivers seat	
164	1		
165	1	Battery "ON" indicator:	0.00
166	4	Green indicator OEM installed on dash	
167	1		
168	-	Alternato <u>r:</u>	0.00
169	1	320A OEM installed	
170			
171	1	Auto-Throttle:	
172	1	Interface electronic engine	100.00
173	1		
174]		
175]		
176		120 Volt System	
177			
178		<u>Shoreline # 1:</u>	150.00
179	1	Kussmaul 20A Super Auto-Eject	363.00
180	1	Power Source For: Battery charger & interior outlets	
181	4		
182	4	Positions TBA due to tail light package	
183	4		150.00
184	4	Shoreline # 2:	150.00 363.00
185	4	Kussmaul 20A Super Auto-Eject	303.00
186	4	Power Source For: Roof top air conditioner	
187	4	Circuit Depaker Banah	250.00
188	4	Circuit Breaker Panel:	200.00
189	4	Square "D" panel with (2) 20A GF1 circuit breakers	200.00
190	4	Downer Strip 1201/1	100.00
191	4	Power Stylp 120V: Six (6) outlets	60.00
192	4	Compartment # 7	00.00
193	-		
194	1	Location: vertical right on wall # 3 - flush with top cmpt. Panel	
194	4	Lookion, vortion fight of that # 0 - fuor with top only. I dior	
195	4	•	
190	<u> </u>		

1

2. î

	A	В	С
197		<< ICC & DOT LIGHTING & REQUIRED DEVICES >>	L
198		*	
199			
200		Clearance and Marker Lights:	100.00
201		Weldon LED's with S/S guards	80.00
202		Standard ICC/DOT body reflectors.	
203		Back Up Alarm:	
204		DOT approved back up alarm.	50.00
205		Tail Light Housing:	
206		Interface with new chassis	100.00
207		Brake/Tail Lights:	
		Whelen 900 Series Red lens # 90R00XRR with flange - (2)	
208		each	560.00
209		Turn Signals:	
		Whelen 900 Series Amber Guide Arrows # 90A00TAR with	
210		flange - (2) each	464.00
211		5 ()	
212			
213		*	
214		<< K.K.K. SAFETY PLACARDS >>	
215		*	
216			
217		Product Logo:	
218		Two (2) Medicmaster™ name plates.	
219		Seat Belt Warning Sign:	
220		1. Cab.	15.00
221		No Smoking/Oxygen Sign:	
222		1. Cab.	15.00
223		Star of Life Certification:	
224		As required.	
225		Payload Weight Certification:	
226		As required.	
227		FMVSS Label:	
228		As required.	
229		AMD Label:	
230		As required.	
231			
232			
233		*	
234		<< AUDIBLE EMERGENCY WARNING DEVICES >>	
235		*	
236			
237		Electronic Siren:	150.00
238		Remove & reinstall	
239			
240		Speakers:	
241		R & R both speakers	150.00
242			
243		Air Homs:	
244	-	Install button to activate horns - upper center of dash plate	150.00

.1

• •

гт	A	В	С
245		OEM floor switch	
246			
247		*	
248		<< VISUAL WARNING DEVICES >>	
249		*	
250			
251		Front Light Bar:	400.00
252		Whelen Model 5000KKF LED	1,550.00
253		Lens Configuration: RRRCRRR	
254		•	
255			
256		Rear Light Bar:	400.00
257		Whelen Model 5000KKF LED	1,400.00
258		Lens Configuration: RRRCACRRR	
259		Switch As: Rear Light Bar	
260			
261		<u>Grill:</u>	100.00
262		Whelen 900 strobe split red/clear with flange	167.00
263		Curbside upper corners of grill.	
264		Primary/Secondary	
265			
266		<u>Grille:</u>	100.00
267		Whelen 900 strobe split red/clear with flange	167.00
268		Streetside upper corners of grill.	
269		Primary/Secondary	
270			400.00
271		Forward Intersector:	100.00
272		Whelen 700 strobe split red/clear with flange	157.00
273		Streetside engine cowling	
274		Primary/Secondary	
275 276		Ferward Internation	100.00
270		Forward Intersector: Whelen 700 strobe split red/clear with flange	157.00
278		Curbside engine cowling	107.00
279		Primary/Secondary	
280			
281		Rear Intersector:	100.00
282		Whelen 700 strobe - red lens with flange	147.00
283		Center above rear wheel wells	
284			
285		Rear Intersector:	100.00
286		Whelen 700 strobe - red lens with flange	147.00
287		Center above rear wheel wells	
288			
289		<u>Rear Modular Body:</u>	325.00
290		Whelen 900 LED amber lens with flange	100.00
291		Streetside - midlevel - position upper window level	
292		Primary/Secondary	
293			
294		<u>Rear Modular Body:</u>	325.00

ŧ

[]	A	В	С
295		Whelen 900 LED amber lens with flange	100.00
296		Curbside - midlevel - position upper window level	100.00
297		Primary/Secondary	
298		, initially coolineary	
299		LED Flasher:	100.00
300		Weldon LED flasher	110.00
301			
302		Strobe Power Supply:	200.00
303		Whelen UPS 690	473.00
304			
305		Spotlight:	100.00
		Collins Model #CL-12 <> hardwire <> aluminum holster right	
306		side of center console	160.00
307			
308		Block Heater:	0.00
309		None	
310			
311		Interior 120 Receptacles:	50.00
312		Check for proper operation - R & R if necessary	
313			
314		Rear Step Bumper.	100.00
315		Install new bumper	750.00
316		Dock Bumper: Yes	50.00
0.17		Reflective Stripe: Red/White on rear facing face of hinged	
317		section	25.00
318			
319 320		Compartment Lighting:	0.00
320		Check all lights for proper operation	
322		Modular Body Doors:	350.00
		Check each door for proper timing, & worn out items.	350.00
323		Replace or repair as necessary	
324			
325			
326			
327		PATIENT COMPARTMENT	
328			
329			
330		Air Conditioner/Heat Unit:	
		Replace air conditioning cabinet on upper forward bulkhead.	
		Install top hinged door, (2) gas struts, return air vents, and	
331		new cushion under cabinet	760.00
		Install new Hoseline Model ACHU1128R air conditioning	
332	(evaparator and accessories	2,600.00
333			
334		Roof AC/Heat Unit:	1,200.00
335		Duothrem Penguin	645.00
336		Distribution Box - polar white	90.00
337			110.00
338		Thermostat - action aera wall	

,

. .

	A	В	С
339	<u>├</u>	Electric heat strip 5,600 BTU	
340	1	Curbside roof above the stepwell	
- 040	ł	Condensation drain lines shall terminate in a catch basin	
341		under modular body - Quarter turn drain valve to empty pan	350.00
342	{	Power AC with shoreline	550.00
		Install roof pan to prevent condensation runoff when unit is	
343		parked on a 10 degree angle	
		Deflector Shield188" with 6"H X 18"W openiings - (1)	
344		forward & (2) each side	550.00
	1	Angle forward & rear vertical sides of openings so they align	500.00
345		with the front slant of the shield - both side openings	100.00
346	1	Clearance Sign: TBA	100.00
347		Oleanance olgin. TDA	
348		Floor:	1,500.00
349		Install Lonseal II # 421 Mica flooring	350.00
350		moule conocaritine set i mou nooring	000.00
351	1	Uphoistery:	1,000.00
352		Replace all uphoistery	400.00
353			-100.00
354		Interior Repairs;	
355		Repair latch on squad bench	50.00
356		Replace (2) Jedcos on squad bench	50.00
357		Replace all interior gas struts	50.00
358		Struts	150.00
359		Replace Southco latch at forward end of squad bench	25.00
360			
361		Fans 12V Non-Oscillating:	
362		Two (2) Bergstrom Model #756360 fans.	100.00
363		1. Streetside wall at rear cabinet	100.00
364		2. Wall left of the AC access door	100.00
365			
366			
367			
368		Total	87,620.00
		· · · · · · · · · · · · · · · · · · ·	

.

	A	В	С
1			<u> </u>
2		*	
3			
4		Remount # 4	
5			
6			
7	· ·	Work Order Number:	
8			
9		Date:	
10		2-18-2003	
11			
12		·	
13			
14		•	
15		Primary Contact Person:	
16		Jay Bridenthal - Supervisor	
17		(941) 335-1623 - Phone	
18		(941) 930-8618 - Pager	
19		(941) 335-1638 - Fax	
20		bridenja@leegov.com	
21		rawlinml@leegov.com	
22		Contact Person:	
23		Chris Hansen - Program Manager	
23		Richard (Rocco) Cranford - Operations Manager	
24		Telephone:	
		(941) 335-1600 - Main Number	
26		• •	
27		(941) 335-1604 - Chris	
28		(941) 335-1636 - Rocco	
		(941) 338-3239 Danny Brashear & Randy Feinstein & Mark	
29		Clugston - Fleet Management	
30		(239) 338-3234 - Shop Fax	
31		brashedr@leegov.com	
32		Fax Number:	
33		(941) 335-1638	
34			
35			
36			ŝ
37			
38		Plant Contact:	
39		Bob ivey	
40			
41		Delivery Point (F.O.B.):	
42		Fort Myers, Florida	
43			
44		Transportation:	
45		Fort Myers to Sanford	400.00
46		Sanford to Fort Myers	400.00
47		,	700.00
48		*	
49		CAB & CHASSIS	
		CIDENTLY # UNV	

. .

	A	В	С
50		*	
51			
52	l		. [
53	ĺ	Chassis Manufacturer:	46,761.90
54	1	Freightliner	
55		Chassis Model:	
56	1	FL-60 (2) door Cab	
57		Chassis Model Year:	
58		2003/4	
59	1	VIN#:	
60	1		
61	1	Engine:	
62	1	Mercedes MBE900 - 210HP	
63	{	Transmission:	4
64	1	Allison 2400 Series - 5 speed - "T" Shifter with park Pawl	
65	4	Brakes:	
66	1	Air	
	{		
67	ł	*	
68	ł	CHASSIS PREPARATION	
69 70	ł	500000 FREFARATION *	
70			
71	ł	Demount medules hade - 24 hours	1 000 00
72	Į	Demount modular body - 24 hours	1,200.00
73	ł	Remount modular body - 40 hours	2,000.00
74		Disconnect Electrical, AC, Heater, ETC - 16 hours	800.00
75			
76		Tow Hooks Or Eyes:	0.00
77		Rear: None	
78			
79		Fuel Tank Cover/Entry Step:	
80		Move existing cover	200.00
		Fuel tank cover with step on passengers side100" diamond	
81		plate aluminum.	
82		45 gallon fuel tank	l
83		hours - (4)	
84			ļ
85		Battery Storage/Entry Step:	1
86		Install new battery box - materials	950.00
87		Hours - (6)	300.00
88		Slideout battery tray with step on drivers side.	
89		Material: .100" diamond plate aluminum.	Ì
90			Į
91		Air Ride Suspension:	100.00
92		Interface with existing system	
93			
94		Exhaust System:	400.00
			ļ
95		Exit at a 45 degree angle forward of the streetside wheel well	l.
96			
97		Cab And Module Passage-Way:	400.00

.

, . 1 I

	A	В	С
98	A	Walk thru with no door	55.00
99		hours - (8)	55.00
100			
100		*	
101		PAINT, LETTERING & STRIPING	
102		FAINT, LEFTERING & STRIFING	
103			
105		Primary Paint:	
106		Brand: PPG	7,500.00
107		Color: White	7,000.00
108		Paint Number: DHUS-2185	
109		Location: Total unit	
110		Bead Blast: Module	1,100.00
111		Zolatone Compartments: Gray	500.00
112		R & R modular body components	2,000.00
113		n a n modular body components	2,000.00
114		Reflective Striping & Graphics:	800.00
115		See pictures in file	150.00
116			100.00
117		Undercoating:	50.00
118		Front wheel wells	30.00
119			
120		*	
121		<< CAB AREA >>	
122		*	
123			
124		Rocker Switch Panel:	100.00
125		Transfer	
126			
127		Cab Console:	500.00
128		Install new console - Design TBA	300.00
129		Material	150.00
130			
131		Door Open Warning Panel:	50.00
132		Transfer	
133		Ma Mara A and	
134 135		Voltmeter: Transfer	50.00
135		1 1 di 13171	
130		Ammeter:	50.00
138		Transfer	50.00
139		4	
140		Dash Protective Plate:	100.00
141		Install .100" smooth aluminum plate "DA" finished	10.00
142			10.00
143		Power Supply:	50.00
144		Install cigar lighter receptacle in center console	10.00
145		,	
146		*	
147		<< 12v DC ELECTRICAL SYSTEM >>	

,

.

	Α	В	С	
148		*		
149				
150		<u>Electrical:</u>		
151		Disconnect cab harness & reinstall	2,000.00	I
152		General electrical hours	5,000.00	I
153				
154		Batteries:	0.00	
155		Four (4) GP31's in slideout tray left step.		
156				
157		Battery Switching:	0.00	
158		Paddle on/off - Left of drivers seat		
159				
160		Battery "ON" indicator:	0.00	
161		Green indicator OEM installed on dash		
162				
163		Alternator:	0.00	
164		320A OEM installed		
165				
166		Auto-Throttle:		
167		Interface electronic engine	100.00	
168				
169				
170				
171		120 Volt System		
172				
173		Shoreline # 1:	150.00	
174		Kussmaul 20A Super Auto-Eject	363.00	
175 176		Power Source For: Battery charger & interior outlets		
177		Positions TBA due to tail light package		
178		r uskions ron due to tair light package		
179		Shoreline # 2:	150.00	
180		Kussmaul 20A Super Auto-Eject	363.00	
181		Power Source For: Roof top air conditioner	000.00	
182				
183	I	<u>Circuit Breaker Panel:</u>	250.00	
184		Square "D" panel with (2) 20A GFI circuit breakers	200.00	
185				
186	1	Power Strip 120V:	100.00	
187		Six (6) outlets	60.00	
188	(Compartment # 7		
				1
189	1	Location: vertical right on wall # 3 - flush with top cmpt. Panel		
190		ſ ·		1
191		*		
192		<< ICC & DOT LIGHTING & REQUIRED DEVICES >>		
193		* * * * * * * * * * * * * * * * * * *		, ;
194				
195	<u>c</u>	Clearance and Marker Lights:	100.00	
196	<u> </u>	Neldon LED's with S/8 guards	80.00	

,

	····	r <u> </u>	
	<u>A</u>	B	C
197		Standard ICC/DOT body reflectors.	
198		Back Up Alarm:	50.00
199		DOT approved back up alarm.	50.00
200		Tail Light Housing:	
201		Interface with new chassis	100.00
202		Brake/Tail Lights:	
		Whelen 900 Series Red lens # 90R00XRR with flange - (2)	
203		each The Atlanta	560.00
204		Turn Signals:	
0.00		Whelen 900 Series Amber Guide Arrows # 90A00TAR with	
205		flange - (2) each	464.00
206			
207			
208			
209		<< K.K.K. SAFETY PLACARDS >>	
210		*	
211		Burn Hand Landa	
212		Product Logo:	
213		Two (2) Medicmaster™ name plates.	
214		Seat Belt Warning Sign:	
215		1. Cab.	15.00
216		No Smoking/Oxygen Sign:	
217		1. Cab.	15.00
218		Star of Life Certification:	
219		As required.	
220		Payload Weight Certification:	
221 222		As required.	
222		FMVSS Label:	
223		As required. AMD Label:	
224		As required.	
226		As lequireu.	
220			
228		*	
229		<< AUDIBLE EMERGENCY WARNING DEVICES >>	
230			
231			
232		Electronic Siren:	150.00
233		Remove & reinstall	100.00
234			
235		Speakers:	
236		R & R both speakers	150.00
237		· · · · ·	100.00
238		Air Horns:	
239		Install button to activate horns - upper center of dash plate	150.00
240		OEM floor switch	100.00
241			
242		۰. ۲	
243		<< VISUAL WARNING DEVICES >>	
244		*	

, . • •

245 246 247 248		
247	Energy Light Down	
	Front Light Bar:	400.00
248	Whelen Model 5000KKF LED	1,550.00
	Lens Configuration: RRRCRRR	
249		
250		
251	Rear Light Bar:	400.00
252	Whelen Model 5000KKF LED	1,400.00
253	Lens Configuration: RRRCACRRR	
254	Switch As: Rear Light Bar	
255		
256	<u>Grill:</u>	100.00
257	Whelen 900 strobe split red/clear with flange	167.00
258	Curbside upper corners of grill.	
259	Primary/Secondary	
260		
261	<u>Grille:</u>	100.00
262	Whelen 900 strobe split red/clear with flange	167.00
263	Streetside upper corners of grill.	
264	Primary/Secondary	
265		
266	Forward Intersector:	100.00
267	Whelen 700 strobe split red/clear with flange	157.00
268	Streetside engine cowling	
269	Primary/Secondary	
270	P 11.4	400.00
271	Forward Intersector:	100.00
272	Whelen 700 strobe split red/clear with flange	157.00
273	Curbside engine cowling	
274	Primary/Secondary	
275	Dear interrector	100.00
277	Rear Intersector: Whelen 700 strobe - red lens with flange	147.00
278	Center above rear wheel wells	147.00
279		
2/9	Rear Intersector:	100.00
281	Whelen 700 strobe - red lens with flange	147.00
282	Center above rear wheel wells	
283		
284	Rear Mod <u>ular Body:</u>	325.00
285	Whelen 900 LED amber lens with flange	100.00
286	Streetside - midlevel - position upper window level	
287	Primary/Secondary	
288		
289	Rear Modular Body:	325.00
290	Whelen 900 LED amber lens with flange	100.00
291	Curbside - midlevel - position upper window level	
292	Primary/Secondary	
293		
294	LED Flasher:	100.00

,

.

2

.

•

	A	В	С
295	~	Weldon LED flasher	110.00
296			
297		Strobe Power Supply:	200.00
298		Whelen UPS 690	473.00
299			
300		Spotlight:	100.00
		Collins Model #CL-12 <> hardwire <> aluminum holster right	
301		side of center console	160.00
302			
303		Block Heater:	0.00
304	1	None	
305_			
306		Interior 120 Receptacles:	50.00
307		Check for proper operation - R & R if necessary	
308			400.00
309		Rear Step Bumper:	100.00
310		Install new bumper	750.00
311		Dock Bumper: Yes	50.00
		Reflective Stripe: Red/White on rear facing face of hinged	25.00
312		section	23.00
313			0.00
314		Compartment Lighting: Check all lights for proper operation	0.00
315		Check all lights for proper operation	
316 317		Modular Body Doors:	350.00
- 517		Check each door for proper timing, & worn out items.	
318		Replace or repair as necessary	sť.
319			
320			
321			
322		PATIENT COMPARTMENT	
323		•	
324		,	
325		Air Conditioner/Heat Unit:	
		Replace air conditioning cabinet on upper forward bulkhead.	
1		Install top hinged door, (2) gas struts, return air vents, and	
326		new cushion under cabinet	760.00
		Install new Hoseline Model ACHU1128R air conditioning	
327		evaparator and accessories	2,600.00
328			4 000 00
329		Roof AC/Heat Unit:	1,200.00
330		Duothrem Penguin	645.00 90.00
331		Distribution Box - polar white	90.00 110.00
332		Electronic Kit Thermostat - action aera wall	110.00
333		Electric heat strip 5,600 BTU	
334		Curbside roof above the stepwell	
- 335		Condensation drain lines shall terminate in a catch basin	
336		under modular body - Quarter turn drain valve to empty pan	350.00
337		Power AC with shoreline	000.00
007			

.

:

٠.

.

· · · ·	A	В	С
		Install roof pan to prevent condensation runoff when unit is	
338		parked on a 10 degree angle	
		Deflector Shield188" with 6"H X 18"W openiings - (1)	
339		forward & (2) each side	550.00
		Angle forward & rear vertical sides of openings so they align	
340		with the front slant of the shield - both side openings	100.00
341		Clearance Sign: TBA	
342			
343		Floor:	1,500.00
344		Install Lonseal II # 421 Mica flooring	350.00
345			
346		<u>Upholstery:</u>	1,000.00
347		Replace all uphoistery	400.00
348			
349		Interior Repairs:	
350		Repair latch on squad bench	50.00
351		Replace (2) Jedcos on squad bench	50.00
352		Replace all interior gas struts	50.00
353		Struts	150.00
354		Replace Southco latch at forward end of squad bench	25.00
355			
356		Fans 12V Non-Oscillating:	
357		Two (2) Bergstrom Model #756360 fans.	100.00
358		1. Streetside wall at rear cabinet	100.00
359		2. Wall left of the AC access door	100.00
360			
361			
362			
363	<u> </u>	Total	96,926.90

ć

rT	A	В	С
		CUSTOMER INFORMATION	
		*	
2			
3			
4			
5		Work Order Number:	
6			
7		<u>Date:</u>	
8		2-18-2003	
9		4-4-2003	
10		4-9-2003	
11		4-11-2003	
12			
13		Primary Contact Person:	
14		Jay Bridenthal - Supervisor	
15		(239) 335-1623 - Phone	
		(239) 930-8618 - Pager	
16		(239) 335-1638 - Fax	
17			
18		bridenja@leegov.com	
19		rawlinml@leegov.com	
20		Contact Person:	
21		Chris Hansen - Program Manager	
22		Richard (Rocco) Cranford - Operations Manager	
23		Telephone:	
24		(239) 335-1600 - Main Number	
25		(239) 335-1604 - Chris	
26		(239) 335-1636 - Rocco	
		(239) 338-3239 Danny Brashear & Randy Feinstein & Mark	
27		Clugston - Fleet Management	
28		(239) 338-3234 - Shop Fax	
29		brashedr@leegov.com	
30		Fax Number:	
31		(239) 335-1638	
32			
33			
34			
35			
		Plant Contact:	
36			
37		Bob lvey	
38		The Hard and A COLOR A	
39		Delivery Point (F.O.B.):	
40		Fort Myers, Florida	
41		Date & Time prearranged with Jay Bridenthal	
42		Transportation:	400.00
43	l	Fort Myers to Sanford	400.00
44		Sanford to Fort Myers	400.00
45			
46		Lodging & Meals:	
47		(1) personnel per trip - (2) trips	0.00
48			
49		Battery Storage/Entry Step:	

۰. *۱*.

		······	
	A	B	C
50		Install new battery box - materials	950.00
51		Hours - (6)	300.00
52		Slideout battery tray with step on drivers side.	
53]	Material: .100" diamond plate aluminum.	
54		Rubrail with reflective strip	
55			
56		Curbside Entry Step - Fuel Tank Cover:	300.00
57		Material: .100" diamond plate aluminum.	150.00
58		Rubrail with reflective strip	
59			
60] •		
61		Primary Paint:	
62]	Brand: PPG	7,500.00
63	1	Color: White	•
64	1	Paint Number: DHUS-2185	
65	1	Location: Total unit	
66	1	Bead Blast: Module	1,100.00
67	1	Zolatone Compartments: Gray	500.00
68	4	R & R modular body components	2,000.00
69	4	Paint & Supplies:	1,100.00
70		F1	1,100.00
71		Reflective Striping & Graphics:	800.00
72	4	See pictures in file	150.00
73			100.00
74			
75		*	
76		<< CAB AREA >>	
77		*	
78			
79		Center Console:	100.00
		Recondition the console. Install aluminum edging to protect	100.00
80		the edges. Replace any damaged switches.	
81		and any damaged enterior.	
82		Cab Seats:	400.00
	•		400.00
83		Install (2) new Bostrom cab seats - reuse existing seat bases	800.00
84		Return old seats to customer	000.00
85			
86		Cab Interior Door Panels:	200.00
87		Replace streetside interior door panel	183.00
88		Replace curbside interior door panel	
89		ropiace carbone antenor door parter	183.00
90	(<u>Cab Door Seals:</u>	100.00
91		Replace streetside door gasket/seal	100.00
92		Replace curbside door gasket/seal	87.40
92		nepiace cuinaide door gaakeraedi	87.40
93 94	-	Trach Can Brackat	450.00
94		Trash Can Bracket:	150.00
95 96		Location: Curbside extended cab rear of passengers seat	55.00
		Bracket to retain a 28 quart trash can - see pictures	
97		Ship trash can installed	

≠, •,

r

	A	В	С
98	· <u>····</u> ····		······································
99		Replace Cab OEM Rubber Mats:	300.00
100		Freightliner Part # 18-34248-000 - forward floor mat	346.90
101			
102		Rear View Mirror:	50.00
103		Mirror	25.00
104			
105		Map Light:	50.00
106		Intertek 12" with # 1156 bulb - # WKL-17012	38.75
107		Location: Left upper corner of passengers side dash plate	
108			
109		Voltmeter:	50.00
110		New Gauge	50.00
111			
112		Ammeter:	50.00
113		New Gauge	75.00
114			
115		Dash Protective Plate:	100.00
116	:	Install .100" smooth aluminum plate "DA" finished	10.00
117		Air How Dutters	50.00
118		Air Horn Button: Install button on dash	50.00
119 120		Install button on dash	20.00
120		Grab Handle:	50.00
121		Install HND39916 in passengers side of dash	15.00
122		made in the observers and of dash	15.00
124		Power Supply:	50.00
125		Install cigar lighter receptacle in center console	10.00
126		Passengers side	10.00
127			
128		Power Strip 120V:	100.00
129		Six (6) outlets	80.00
130		Compartment # 7	
		·	
131		Location: vertical right on wall # 3 - flush with top cmpt. Panel	
132		÷	
133		Power Plug:	100.00
134		Cigar Lighter Style: 12VDC >Dual Outlets<	20.00
135		Location: Compartment # 7 next to power strip	
136		Battery hot	
137			:
138		Clearance and Marker Lights:	100.00
139		Weldon LED's with S/S guards	80.00
140			
141		General Electrical Hours:	2,500.00
142			
143		*	
144		<< VISUAL WARNING DEVICES >>	
145		*	
146			

[]	Α	B	С
147		Front Light Bars:	700.00
		Whelen Mini Edge Model 9MMEDFFD Strobes- red/clear lens	
148		- (2) each	1,628.00
149		Angle mount on cab roof	,,
150		Reinforce interior cab roof	100.00
151			
152		Emergency Light Lens:	100.00
153		Replace (2) 97 split red/clear lens	132.00
154		Replace (1) 97 clear lens	24.00
155		Replace (6) 97 red lens	144.00
156			
157		Rear Light Bar:	200.00
158		Rebuild 4000 Series lightbar	
159		Replace (11) lens & (2) end caps	273.00
160		Replace (4) motor/light assemblies	240.00
161			
162		Rear Step Bumper:	150.00
163		Install new bumper	750.00
164		Dock Bumper: Yes	50.00
		Reflective Stripe: Red/White on rear facing face of hinged	
165		section	25.00
166			
167		Compartment Lighting:	50.00
168		Check all lights for proper operation - repair as necessary	
169			
170			
171		PATIENT COMPARTMENT	
172			
173			
174		Air Conditioner/Heat Unit:	1,500.00
		Replace air conditioning cabinet on upper forward bulkhead.	
475		Install top hinged door, (2) gas struts, return air vents, and	
175		new cushion under cabinet	760.00
470		Install new Hoseline Model ACHU1128R air conditioning	
176 177		evaparator and accessories	2,300.00
178		Fane 12V Non Oscillating:	
179		Fans 12V Non-Oscillating: Two (2) Bergstrom Model #756360 fans.	160.00
180		1. Streetside wall at rear cabinet	150.00
181		2. Wall left of the AC access door	105.00 105.00
182			103.00
183		Floor:	1,500.00
184		Install Lonseal II # 421 Mica flooring	350.00
185			000.00
186		Upholstery:	1,000.00
187		Replace all upholstery	445.00
188		······································	770.00
189		Interior Repairs:	
190		Repair latch on squad bench	50.00
191		Replace (2) Jedcos on squad bench	50.00

.

Ť

r			
	A	B	C
192		Replace all interior gas struts	50.00
193		Struts	150.00
194		Replace Southco latch at forward end of squad bench	50.00
195		General Interior Repairs	500.00
196		Replace Lexan as necessary	
197		Check bellows area for leaks and wear -repair if needed	
198		Replace all non-skid floor strips	
199			
200			
201		Interior 120 Receptacles:	50.00
202		Check for proper operation - R & R if necessary	
203			
204		EKG/Monitor Shelf:	100.00
ŀ		Life Pak Bracket - See pictures in notebook - 6 1/4"D - 1 7/16"	
		H - 20" W heavy duty strap with >plastic< buckle. Ship this	
205		loose	100.00
206			
207		Curbside Rear Cabinet Modification:	
		Install new door with (2) metal vents - locking lever latch - (3)	
208		heavy duty plastic hinges - coated cable door restraints	1,200.00
209		Install (2) drawers behind the new door.	150.00
210		This cabinet should mirror as close as possible the new units.	
211	_		
212			
213		EXTERIOR COMPARTMENTS/MOD. BODY	
214			
215		Compartment # 1:	
		Install rubber bumpers >rubrail< on wall # 1, # 2, and	
216		forward facing side of the divider	150.00
217		Level # 1: 12" above floor	50.00
218		Level # 2: 60" above floor	
219		Strap: 36" above floor - forward section	
220		· · · ·	
221		Compartment Decking:	100.00
		Install "black" Turtle Tile in compartment decks - forward	
222		edge to have "beveled" forward edges.	140.00
223		Compartments #: 1,2,4,5,6	
224			
225		Modular Body Rubrails:	500.00
226		Install new rubrails with reflective strips	405.00
227		Reflective Color: White	
228			
229		Modular Body Doors:	350.00
		Inspect each interior door mechanism for proper operation,	
230		worn hardware, and replace as necessary	
231	1	Materials: Replace gaskets, seals as necessary	250.00
232			
233	-	Rear Doors:	50.00
234		Replace (4) Cast Products Grabbers	105.28

F F	A	B	C
235			
236		Waste Container/Bracket:	250.00
237		Location: Curbside entry door	100.00
		Stainless Steel Bracket for a 28 guart Rubbermaid container -	
238		ship container installed -	
239		Mount container bracket on door low as possible	
240		•	
		In order to price the replacement of the diamond plate.	
241		would need to see the unit to take measurements	
242			
243			
244		Total	39,997.73
245			
246			
247			
248		1	

÷