

Lee County ADA Structural Transition Plan FY19

Key
DOT = Department of Transportation
LIB = Library Services
FAC = Facilities and Construction Management
LTRN = Lee Tran
PR = Parks and Recreation

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
DOT - 6513	Daniels Parkway & Gateway Boulevard	Priority Rank: 1 - Signal		FY17	ADA - Engineering design services/bid work
DOT - 6514	Lee Boulevard & Sunshine Boulevard	Priority Rank: 1 - Signal		FY17	ADA - Engineering design services/bid work
DOT - 4317	Gunnery Road N & 12 St W	Priority Rank: 1 - Signal		FY17	ADA - Engineering design services/bid work
DOT - 6109	Gunnery Road S & 23rd Street SW	Priority Rank: 1 - Signal		FY17	ADA - Engineering design services/bid work
DOT - 10015	Gunnery Road & Lee Boulevard	Priority Rank: 1 - Signal		FY17	ADA - Major maintenance budget
DOT - 2206	Corkscrew Road & Via Coconut Point	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 2207	Ben Hill Griffin Parkway & Estero Parkway	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 2208	Three Oaks Parkway & San Carlos Boulevard	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 2209	Ben Hill Griffin Parkway & FGCU	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 2205	Ben Hill Griffin Parkway & College Club Drive	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 603	Ben Hill Griffin Parkway & Gulf Coast Drive/Main Entrance	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 10021	Ben Hill Griffin Parkway & Miromar Lakes	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 606	Ben Hill Griffin Parkway & FGCU Lakes Parkway	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 2202	Alico Road & Quaker Road	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 2203	Corkscrew Road & Three Oaks Parkway	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/bid work FY17
DOT - 10043	Corkscrew Road & River Ranch Road	Priority Rank: 2 - Signal		FY17	ADA - Engineering design services/ FY18 - bid work
DOT - 306	San Carlos Boulevard & Oriole Road	Priority Rank: 2 - Non		FY17	MM budget, funding carried over
DOT - 4221	Homestead Road & Alabama Road	Priority Rank: 3 - Signal	\$17,900,000	FY17	CIP FY18 \$690,000

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
DOT - 10013	Milwaukee Boulevard & Alabama Road	Priority Rank: 3 - Non		FY17	MM - FY18 - bid work
DOT - 10038	Williams Avenue & W 6th Street	Priority Rank: 3 - Non		FY17	MM - FY18 - bid work
DOT - 10039	Richmond Ave & 6th Street	Priority Rank: 3 - Non		FY17	MM - FY18 - bid work
DOT - 6508	Del Prado Boulevard & Veterans Memorial Parkway	Priority Rank: 11 - Signal		FY17	MM budget, funding carried over
DOT - 6510	Del Prado Boulevard & SE 26th Street	Priority Rank: 11 - Signal		FY17	MM budget, funding carried over
DOT - 6511	Del Prado Boulevard & SE 27th Street	Priority Rank: 11 - Signal		FY17	MM budget, funding carried over
DOT - 6512	Del Prado Boulevard & SE 28th Terrace	Priority Rank: 11 - Signal		FY17	MM budget, funding carried over
DOT - 6513	Del Prado Boulevard & Cornwallis Parkway	Priority Rank: 11 - Signal		FY17	MM budget, funding carried over
DOT - 6514	Del Prado Boulevard & SE 32nd Terrace	Priority Rank: 11 - Signal		FY17	MM budget, funding carried over
DOT - 3115	Hancock Bridge Parkway & Moody Road	Priority Rank: 13 - Signal		FY17	MM and Sidewalk budget
DOT - 6109	Joel Boulevard & East 10th Street	Priority Rank: 17 - Non		FY17	MM - Y18 - bid work
DOT - 10031	Lee Boulevard & Leonard Boulevard North	Priority Rank: 18 - Non		FY17	MM - FY18 - bid work
DOT - 10044	Del Prado Boulevard & Coral Point Drive	Priority Rank: 10 - Signal		FY18	Targeted for maintenance
DOT - 2201	Del Prado Boulevard & Coral Point Mall	Priority Rank: 10 - Signal		FY18	Targeted for maintenance
DOT - 2204	Del Prado Boulevard & SE 20th Street	Priority Rank: 10 - Signal		FY18	Targeted for maintenance
DOT - 6515	Del Prado Boulevard & SE 22nd Terrace	Priority Rank: 10 - Signal		FY18	Targeted for maintenance
DOT - 6516	Del Prado Boulevard & SE 12th Terrace	Priority Rank: 10 - Signal		FY18	Targeted for maintenance
DOT - 6517	Buckingham Road & Orange River Boulevard	Priority Rank: 15 - Signal		FY18	MM budget
DOT - Request 1	Earl Road &	Priority Rank: Request for Accommodation - Non		FY18	In Design
DOT - Request 3	Bonita Beach Road & Spanish Wells Boulevard	Priority Rank: Request for Accommodation - Signal		FY18	In Design
DOT - 6518	Pondella Road & Moody Road	Priority Rank: 10 - Signal		FY19	Targeted for maintenance
DOT - 6519	Diplomat Parkway & Corbett Road	Priority Rank: 10 - Non		FY20	Targeted for CIP
DOT - 6601	Pondella Road & April Lane	Priority Rank: 10 - Signal		FY20	Targeted for maintenance
DOT - 6602	Del Prado Boulevard & Bolado Parkway	Priority Rank: 10 - Signal		FY20	Targeted for maintenance

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
DOT - 6605	Del Prado Boulevard & SE 6th Street	Priority Rank: 10 - Signal		FY20	Targeted for maintenance
DOT - 10023	Burnt Store Road & Ceitus Parkway	Priority Rank: 10 - Non		FY20	Targeted for maintenance
DOT - 2701	Ortiz Ave. & Ballard Road	Priority Rank: 9 - Signal		FY21	CIP - Waiting for allocation
DOT - 2702	Ortiz Ave. & Tice Street	Priority Rank: 9 - Signal		FY21	CIP - Waiting for allocation
DOT - 10050	Ortiz Ave. & Luckett Road	Priority Rank: 9 - Signal		FY21	CIP - Waiting for allocation
DOT - 10009	Del Prado Boulevard & NE 6th Street	Priority Rank: 10 - Signal		FY21	Targeted for maintenance
PR - 1	Lehigh Acres Middle School Soccer Fields - General: There are no parking spaces designated at the soccer fields.	Add a concrete slab on the shortest route from soccer field parking lot to the ADA field entrance - Create 3 12' ADA parking spaces w/ 2 5' access aisles create a 44" min. access route in front of the ADA spaces to connect with an ADA entrance gate	\$12,500	FY18	Aug-18
PR - 2	Lehigh Acres Middle School Soccer Fields - no accessible routes that allow a free flow for people with disabilities to specific events, food or restrooms.	Create concrete accessible route 60" min. (running slope no > 1:20 cross slope no > 1:48) with concrete ADA viewing areas	\$14,600	FY18	Aug-18
PR - 3	Lehigh Acres Middle School Soccer Fields - Disability parking spaces none provided, total main parking 0 paved, disability 0 paved.	On concrete parking pad, stripe 3 accessible spaces with adjoining access aisles and ADA access route - markings according to FDOT/Lee County standards - proper signage	\$11,400	FY18	in progress.
PR - 4	Lehigh Acres Middle School Soccer Fields - Entrance is only through the employee parking lot, other parking is a grass field.	Create an accessible entrance to the soccer fields with a gate, operable parts within ADA reach range - operable with closed fist - ADA latch	\$6,750	FY18	Aug-18
PR - 5	Lehigh Acres Middle School Soccer Fields - General: Access to goods and services is non-existent.	Create an accessible route from parking ADA parking area to goods and services.	\$8,500	FY18	Aug-18
PR - 6	Lehigh Acres Middle School Soccer Fields - No access to water fountain.	Water fountain shall be replaced to ADA compliant high/low fountains and be located on the accessible route - not to cause protrusion	\$1,250	FY18	construction in progress.
PR - 7	Lehigh Acres Middle School Soccer Fields - No access to soccer fields.	Create concrete Accessible route shall 60" wide to create access to 2 fields	\$12,500	FY18	Aug-18
PR - 8	Lehigh Acres Middle School Soccer Fields - No access to food stand or restrooms.	Lehigh Acres Middle School Soccer Fields - No access to food stand or restrooms. - Connect access route to ADA access ramp to Restrooms and concession area	\$10,800	FY18	construction in progress.

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
PR - 9	Lehigh Acres Middle School Soccer Fields - Pavilion has more than a ½" edge protection drop-off around access sidewalk and pad.	General maintenance advisory - add fill.	\$1,150	FY18	in progress.
PR - 10	Lehigh Acres Middle School Soccer Fields - No access to restrooms.	Add accessible route/ramp to restrooms.	\$14,900	FY18	Construction in progress.
PR - 11	Lehigh Acres Middle School Soccer Fields - No signage.	Add ADA restroom signage -tactile, Braille, International Symbol location following 703.4	\$175	FY18	in progress.
PR - 12	Lehigh Acres Middle School Soccer Fields - No disability accessible stalls.	Alter restrooms to be ADA compliant	\$6,750	FY18	Construction in progress.
PR - 13	Kelly Soccer Complex -South parking Facility - Disability parking ratio incorrect; Total parking 212, Accessible spaces 6	Kelly Soccer South Complex - Disability parking ratio incorrect; Total parking 212, Accessible spaces 6 - Need to add 1 more accessible parking space.	\$11,500	FY18/19	
PR - 14	Kelly Soccer Complex - South Parking Facility - Parking lines faded	Kelly Soccer Complex - Parking lines faded - Ensure correct dimensions for accessible parking and restripe.	\$0	FY18/19	
PR - 15	Kelly Soccer Complex - South Complex - Uneven surface - vertical changes in level at approach to restroom sidewalk from parking lot.	Kelly Soccer South Complex - Uneven surface - vertical changes in level at approach to restroom sidewalk from parking lot. - Correct uneven surface - no changes in level greater than 1/4"	\$0	FY18/19	
PR - 16	Kelly Soccer Complex - North Parking Facility Disability parking ratio incorrect. Total 58 with 2 ADA spaces, needs 3 ADA spaces.	Reseal and restripe, add another ADA parking space to equal 3.		FY19	
PR - 17	Kelly Soccer Complex - North Parking Facility ADA parking space lines are faded.	Restripe to mark the space prominently according to Florida State Statutes and ADA standards.		FY19	
PR - 18	Kelly Soccer Complex - North Parking Facility ADA parking access route to sidewalk has an uneven surface and changes in level over maximum.	When restriping and resealing fix the gaps and correct changes in level to be compliant.		FY19	
PR - 19	Alva Boat Ramp - Disability parking ratio incorrect; Total parking area; Total 15, Disability 0.	Add Accessible parking spaces following 502 Parking. If different types of parking are provided i.e. vehicle & trailer - an accessible space would be needed for each type.		FY19	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
PR - 20	Alva Boat Ramp - Walking surfaces not stable and firm.	Create an accessible route from parking ADA parking area to amenities and services throughout site following Chapter 4 - accessible routes.		FY19	
PR - 21	Alva Boat Ramp - No accessible route of travel to trash cans and pay station.	When accessible route is constructed, locate trash receptacles and pay station to adjoin route.		FY19	
PR - 22	Alva Boat Ramp - Main restrooms missing signage.	Add ADA restroom signage - tactile, Braille, International Symbol of Accessibility (ISA)		FY19	
PR - 23	Alva Boat Ramp - Side wall grab bar is positioned incorrectly. The side wall grab bar shall extend a minimum of 54" from the rear wall (currently extends 48" from rear wall).	Remount the side wall grab bar to meet ADA standards.		FY19	
PR - 24	Alva Community Park - One protruding railing extension into circulation path.	Alva Community Park - One protruding railing extension into circulation path.		FY18	
PR - 25	Alva Community Park - Kitchen sink not accessible and no under sink pipe insulation.	Alva Community Park - Kitchen sink not accessible and no under sink pipe insulation.		FY18	
PR - 26	Alva Community Park - Electric meters protruding at concession stand.	Alva Community Park - Electric meters protruding at concession stand.		FY18	
PR - 27	Alva Community Park - Main field restrooms missing some under lavatory insulation.	Alva Community Park - Main field restrooms missing some under lavatory insulation.		FY18	
PR - 28	North Fort Myers Pool - both Men's and Women's water closets are mounted too close to the wall.	Relocate the water closets so that the centerline is 16" min. and 18" max. from the side wall (FS604.2) - 17" is recommended.		FY19	Being addressed during pool restoration project.
PR - 29	North Fort Myers Pool - Men's accessible stall hinged door is not self-closing.	Add self-closing hardware to meet ADA standards (FS604.8.1.2)		FY19	Being addressed during pool restoration project.
PR - 30	North Fort Myers Pool - Men's restroom sink height is too high at 36"	Remount the sink to 33" from the finished floor surface (FS606.3)		FY19	Being addressed during pool restoration project.
PR - 31	North Fort Myers Pool - Men's room disability stall paper dispenser is mounted too close to the grab bar.	Remount the paper dispenser to be compliant with the ADA standards (FS609.3).		FY19	Being addressed during pool restoration project.
PR - 32	North Fort Myers Pool - Men's restroom rear grab bar mounted too low at 32."	Remount the rear grab bar so that the top of the gripping surface is a min. of 33" and a max. of 36" (FS609.3), recommended to mount at 34"		FY19	Being addressed during pool restoration project.

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
PR - 33	North Fort Myers Pool - both Men's and Women's accessible restrooms - mirror mounted to high @ 41" to edge of reflective surface.	Remount the mirrors in the Men's and Women's accessible stalls to no greater than 40" from the edge of the reflective surface (FS603.3).		FY19	Being addressed during pool restoration project.
PR - 34	North Fort Myers Pool - both Men's and Women's restroom the hook on the accessible stall door is mounted too high.	Remount the hooks so that they are no greater than 48" from the finished floor.		FY19	Being addressed during pool restoration project.
PR - 35	North Fort Myers Pool - both Men's and Women's changing rooms have no accessible garment hooks.	Remount 5% of the garment hooks to no greater than 48" from the finished floor surface, maintain a clear floor space of 30" by 48" for a forward approach to the garment hooks.		FY19	Being addressed during pool restoration project.
PR - 36	Mantanzas Pass Preserve - no accessible route to map board and bike rack.	Add asphalt to create an accessible ground surface to adjoin the map board and bike rack (FS402).		FY19/20	
PR - 37	Matanzas Pass Preserve - trail brochure box mounted so that the operable part is above the 48" max. height.	Lower the trail brochure box so that the operable part's reach range is no greater than 48" above the ground surface (FS308) recommended at around 44"		FY19/20	
PR - 38	Mantanzas Pass Preserve - Fishing platform does not have an accessible area of lowered railing. At least 25% of the railings at Fishing Piers or Platforms need to have a lowered area no greater than 34" from the finished floor surface.	Lower 25% of the railing on the fishing platform to no greater than 48" from the finished floor.		FY19/20	
PR - 39	Mantanzas Pass Preserve - Fishing platform does not have barrier protection around the railing.	Add barrier protection according to the ADA standards (FS405.9.2).		FY19/20	
PR - 40	Mantanzas pass preserve - boat dock is not accessible.	Create access to the boat dock (FS402, FS1003.2).		FY19/20	
PR - 41	Tanglewood Elementary - No Accessible parking at Soccer Field entrance.	Tanglewood Elementary - No Accessible parking at Soccer Field entrance. - Calculate parking capacity of grass lot, add accessible parking following Table 208.2 Parking Spaces	\$267,299	FY19/20	All five Tanglewood projects included in this cost
PR - 42	Tanglewood Elementary - No accessible route to soccer fields	Tanglewood Elementary - No accessible route to soccer fields - Add 5' wide concrete AR from ADA parking to connect boundaries of both soccer fields following FS402 Running slope no > 5%, cross slope no > 2%.		FY19/20	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
PR - 43	Tanglewood Elementary -- Non-Fixed Bleachers are not accessible	- Non-Fixed Bleachers are not accessible - Locate bleachers along the accessible concrete route. If bleachers remain in the same location add concrete wheelchair spaces at either end of bleachers 36" wide min. and 48" deep min. If the bleachers are frequently moved due to reconfiguration of fields, make bleachers accessible upon request - post signs on requesting accommodations.		FY19/20	
PR - 44	Tanglewood Elementary - Trash receptacles are not on an accessible route.	Tanglewood Elementary - Trash receptacles are not on an accessible route. - Place the trash receptacles abutted to the accessible Route.		FY19/20	
PR - 45	Tanglewood Elementary - Play area is not on an accessible route to the public.	Tanglewood Elementary - Play area is not on an accessible route to the public. - Add 5' wide concrete AR from parking area to connect boundaries of both soccer fields following FS402 Running slope no > 5%, cross slope no > 2%.		FY19/20	
PR - 46	Tanglewood Elementary - Portable Restroom is not on an accessible route.	Tanglewood Elementary - Portable Restroom is not on an accessible route. - Add 5' wide concrete AR from ADA parking area to connect the portable restroom following FS402 Running slope no > 5%, cross slope no > 2%. A 60" by 60" level accessible surface is needed a pull side door with 18" past the latch. Restroom should be level with accessible surface.		FY19/20	
LIB - 41	Cape Coral Library - Equipment Room - FS305,306,309,902.3,707.3	Cape Coral Library - Equipment Room - Assorted equipment room, micro-fiche, etc. needs accessible tables and approach. - FS305,306,309,902.3,707.3		FY18	
LIB - 42	Cape Coral Library - Children's area - FS308	Cape Coral Library - Children's area - Children's area, information forms shelves too high. - FS308		FY18	
LIB - 43	Cape Coral Library - Children's area - FS703.3	Cape Coral Library - Children's area - Children's bathroom not marked as accessible and was not inspected. - FS703.3		FY18	
LIB - 44	Cape Coral Library - Restrooms - FS703.4.1-2	Cape Coral Library - Restrooms - Restroom signage incorrect as well as mounting height. - FS703.4.1-2		FY18	
LIB - 45	Cape Coral Library - Restrooms - FS604.4	Cape Coral Library - Restrooms - Disability stall - seat 21" too high. - FS604.4		FY18	
LIB - 46	Cape Coral Library - Restrooms - FS604.7	Cape Coral Library - Restrooms - Disability stall - toilet paper dispenser mounted too close to grab bar. - FS604.7		FY18	
LIB - 47	Cape Coral Library - Restrooms - FS603.4	Cape Coral Library - Restrooms - Disability stall - mirror too high. - FS603.4		FY18	
LIB - 48	Cape Coral Library - Restrooms - FS603.4	Cape Coral Library - Restrooms - Disability stall - hooks on doors too high. - FS603.4		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 49	Cape Coral Library - Restrooms - FS604.8.1.2	Cape Coral Library - Restrooms - Disability stall - stall doors are not self-closing. - FS604.8.1.2		FY18	
LIB - 50	Cape Coral Library - Restrooms - FS606.3	Cape Coral Library - Restrooms - Disability stall - sinks too high. - FS606.3		FY18	
LIB - 51	Captiva Memorial Library - Parking - FS502.6.1,FLDOT MUTCD	Captiva Memorial Library - Parking - Disability parking spots missing blue lines. - FS502.6.1,FLDOT MUTCD		FY18	
LIB - 52	Captiva Memorial Library - Parking - FS502.3	Captiva Memorial Library - Parking - Bench in front of disability spots blocking access to entrance (could move bench back and to the far corner by ramp). - FS502.3		FY18	
LIB - 53	Captiva Memorial Library - Parking - FS405.9	Captiva Memorial Library - Parking - More than ½ " drop-off on back side of access path in front of disability spots. - FS405.9		FY18	
LIB - 54	Captiva Memorial Library - Main Floor - FS308.2	Captiva Memorial Library - Main Floor - Access to pamphlet racks beyond allowable reach range. - FS308.2		FY18	
LIB - 56	Captiva Memorial Library - Restrooms - FS703	Captiva Memorial Library - Restrooms - Restrooms signage worn. - FS703		FY18	
LIB - 57	Library Captiva Memorial Library - Restrooms - FS604.6	Library Captiva Memorial Library - Restrooms - Female restroom water closet flush handle not located on open side. - FS604.6		FY18	
LIB - 58	Captiva Memorial Library - Restrooms - FS606.5	Captiva Memorial Library - Restrooms - Neither restroom has under lavatory exposed pipe protection. - FS606.5		FY18	
LIB - 59	Captiva Memorial Library - Restrooms - FS604.5.2,609.4	Captiva Memorial Library - Restrooms - Neither restroom has a rear grab bar. - FS604.5.2,609.4		FY18	
LIB - 60	Dunbar Jupiter Hammond Library - Parking - FS502.6	Dunbar Jupiter Hammond Library - Parking - Disability Parking signs incorrect. - FS502.6		FY18	
LIB - 61	Dunbar Jupiter Hammond Library - Parking - FS502.6.1	Dunbar Jupiter Hammond Library - Parking - Disability spots paint faded. - FS502.6.1		FY18	
LIB - 62	Dunbar Jupiter Hammond Library - Entrance - FS406.8,705.1.3	Dunbar Jupiter Hammond Library - Entrance - Entrance/Approach no transition strip and no color contrast. - FS406.8,705.1.3		FY18	
LIB - 63	Dunbar Jupiter Hammond Library - Lobby - FS902.3	Dunbar Jupiter Hammond Library - Lobby - Computer stations for card catalog keyboard too high. - FS902.3		FY18	
LIB - 64	Dunbar Jupiter Hammond Library - Main Floor - FS308.3.1	Dunbar Jupiter Hammond Library - Main Floor - Information racks too high to top of rack. - FS308.3.1		FY18	
LIB - 65	Dunbar Jupiter Hammond Library - Main Floor - FS403.5.1	Dunbar Jupiter Hammond Library - Main Floor - Walkway clearance not available going to children's restroom. - FS403.5.1		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 66	Dunbar Jupiter Hammond Library - Main Floor - FS308	Dunbar Jupiter Hammond Library - Main Floor - Photo copy - money machines too high to operate. - FS308		FY18	
LIB - 68	Dunbar Jupiter Hammond Library - Main Floor - FS308	Dunbar Jupiter Hammond Library - Main Floor - Printers - money machines too high to operate. - FS308		FY18	
LIB - 69	Dunbar Jupiter Hammond Library - Main Floor - FS308	Dunbar Jupiter Hammond Library - Main Floor - Printers - no forward access to computer keyboard or mouse. - FS308		FY18	
LIB - 70	Dunbar Jupiter Hammond Library - Main Floor - FS308	Dunbar Jupiter Hammond Library - Main Floor - Printers - access too high to operate printer. - FS308		FY18	
LIB - 71	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS703	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Non-tactile restroom signs. - FS703		FY18	
LIB - 72	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS308	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Changing tables wall mounted too high. - FS308		FY18	
LIB - 73	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS603.4	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Hooks in stalls too high. - FS603.4		FY18	
LIB - 74	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS603.3	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Mirrors too high. - FS603.3		FY18	
LIB - 75	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS308	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Paper towels dispensers too high. - FS308		FY18	
LIB - 76	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS604.8.1.2	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Stall doors not self-closing. - FS604.8.1.2		FY18	
LIB - 77	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS606.5	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Men's restroom lavatory pipe insulation missing. - FS606.5		FY18	
LIB - 78	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS605.2	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Men's restroom urinals too high. - FS605.2		FY18	
LIB - 79	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - FS604.6	Dunbar Jupiter Hammond Library - Restrooms-Main Lobby - Lady's room flush valve wrong side. - FS604.6		FY18	
LIB - 80	Dunbar Jupiter Hammond Library - Children's Restrooms - FS703.4.2	Dunbar Jupiter Hammond Library - Children's Restrooms - Incorrect signage. - FS703.4.2		FY18	
LIB - 81	Dunbar Jupiter Hammond Library - Children's Restrooms - FS609.4	Dunbar Jupiter Hammond Library - Children's Restrooms - Grab bars too high for children's restroom. - FS609.4		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 82	Dunbar Jupiter Hammond Library - Children's Restrooms - FS603.3	Dunbar Jupiter Hammond Library - Children's Restrooms - Mirror too high. - FS603.3		FY18	
LIB - 83	East Lee County Library - Parking - FS208.2	East Lee County Library - Parking - Employee parking spaces 52, disability 2, short 1. - FS208.2		FY18	
LIB - 84	East Lee County Library - Parking - FS502.6	East Lee County Library - Parking - Several disability parking signs incorrect. - FS502.6		FY18	
LIB - 85	East Lee County Library - Parking - FS502.6.1	East Lee County Library - Parking - Disability spots paint faded. - FS502.6.1		FY18	
LIB - 86	East Lee County Library - Entrance - FS406.8,705.1.3	East Lee County Library - Entrance - Entrance/Approach transition strip worn and no color contrast. - FS406.8,705.1.3		FY18	
LIB - 87	East Lee County Library - Main Floor - FS308	East Lee County Library - Main Floor - Main reservation computer too high. - FS308		FY18	
LIB - 88	East Lee County Library - Main Floor - FS227.3,902.3	East Lee County Library - Main Floor - Computer stations for card catalog keyboard too high, 38". - FS227.3,902.3		FY18	
LIB - 89	East Lee County Library - Main Floor - FS903,903.4	East Lee County Library - Main Floor - Benches along walls under windows throughout the library incorrect. - FS903,903.4		FY18	
LIB - 90	East Lee County Library - Main Floor - FS308.3.1	East Lee County Library - Main Floor - Two information racks too high to top rack. - FS308.3.1		FY18	
LIB - 91	East Lee County Library - Main Floor - FS404.2.9	East Lee County Library - Main Floor - Entrance door to youth services meeting room sticking and pull too hard. - FS404.2.9		FY18	
LIB - 92	East Lee County Library - Main Floor - FS308	East Lee County Library - Main Floor - Youth services coat hanger too high to hanger hook. - FS308		FY18	
LIB - 93	East Lee County Library - Main Floor - FS228,309,707.7.1	East Lee County Library - Main Floor - Photo copy room. - FS228,309,707.7.1		FY18	
LIB - 94	East Lee County Library - Copy Room - FS308	East Lee County Library - Copy Room - Photo copy room - money machines too high to operate. - FS308		FY18	
LIB - 95	East Lee County Library - Copy Room - FS308	East Lee County Library - Copy Room - Photo copy room - no access to computer, computer keyboard or mouse. - FS308		FY18	
LIB - 96	East Lee County Library - Copy Room - FS308	East Lee County Library - Copy Room - Photo copy room - no access to printer. - FS308		FY18	
LIB - 97	East Lee County Library - Copy Room - FS308	East Lee County Library - Copy Room - Photo copy room - no access to photo copy machine. - FS308		FY18	
LIB - 98	East Lee County Library - Print Room - FS308	East Lee County Library - Print Room - Money machines too high to operate. - FS308		FY18	
LIB - 99	East Lee County Library - Print Room - FS308	East Lee County Library - Print Room - No access to computer, computer keyboard or mouse. - FS308		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 100	East Lee County Library - Print Room - FS308	East Lee County Library - Print Room - No access to printer. - FS308		FY18	
LIB - 101	East Lee County Library - Print Room - FS308	East Lee County Library - Print Room - No access to photo copy machine. - FS308		FY18	
LIB - 102	East Lee County Library - Main Lobby Restrooms - FS703.4.2	East Lee County Library - Main Lobby Restrooms - No signage in entrance lobby indicating restrooms. - FS703.4.2		FY18	
LIB - 103	East Lee County Library - Main Lobby Restrooms - FS604.4	East Lee County Library - Main Lobby Restrooms - Men's room toilet too high. - FS604.4		FY18	
LIB - 104	East Lee County Library - Main Lobby Restrooms - FS604.8.1.2	East Lee County Library - Main Lobby Restrooms - Men's room stall door not self-closing. - FS604.8.1.2		FY18	
LIB - 105	East Lee County Library - Main Lobby Restrooms - FS604.6	East Lee County Library - Main Lobby Restrooms - Ladies room flush valve wrong side. - FS604.6		FY18	
LIB - 106	East Lee County Library - Main Lobby Restrooms - FS604.8.1.2	East Lee County Library - Main Lobby Restrooms - Ladies room stall door not self-closing. - FS604.8.1.2		FY18	
LIB - 107	East Lee County Library - Youth Services Restrooms - FS604.9	East Lee County Library - Youth Services Restrooms - Boy's restroom toilet too high. - FS604.9		FY18	
LIB - 108	East Lee County Library - Youth Services Restrooms - FS606.5	East Lee County Library - Youth Services Restrooms - Boy's restroom lavatory pipe insulation missing. - FS606.5		FY18	
LIB - 109	East Lee County Library - Youth Services Restrooms - FS603.4	East Lee County Library - Youth Services Restrooms - Boy's restroom hooks too high. - FS603.4		FY18	
LIB - 110	East Lee County Library - Youth Services Restrooms - FS604.7	East Lee County Library - Youth Services Restrooms - Boy's restroom toilet paper holder mounted too close to grab bar. - FS604.7		FY18	
LIB - 111	East Lee County Library - Youth Services Restrooms - FS606.5	East Lee County Library - Youth Services Restrooms - Girl's restroom lavatory pipe insulation missing. - FS606.5		FY18	
LIB - 112	East Lee County Library - Youth Services Restrooms - FS603.4	East Lee County Library - Youth Services Restrooms - Girl's restroom hooks too high. - FS603.4		FY18	
LIB - 113	East Lee County Library - Youth Services Restrooms - FS604.7	East Lee County Library - Youth Services Restrooms - Girl's restroom toilet paper holder mounted too close to grab bar. - FS604.7		FY18	
LIB - 114	East Lee County Library - Youth Services Restrooms - FS604.9	East Lee County Library - Youth Services Restrooms - Girl's restroom toilet too high. - FS604.9		FY18	
LIB - 115	Fort Myers Regional Library - Parking Lot - FS502.6.1	Fort Myers Regional Library - Parking Lot - 2 new disability parking spots in middle of lot, signage at 98". - FS502.6.1		FY18	
LIB - 116	Fort Myers Regional Library - Talking Books (South Annex) - FS404.2.9	Fort Myers Regional Library - Talking Books (South Annex) - Entrance door at 9.5# pull. - FS404.2.9		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 117	Fort Myers Regional Library - Restrooms - FS604.9	Fort Myers Regional Library - Restrooms - Kids Zone Restrooms are marked as Girls/Boys/HP. All fixtures are not to Children compliance. Bring into compliance or change signage. - FS604.9		FY18	
LIB - 118	Fort Myers Regional Library - Restrooms - FS604.8.1.2	Fort Myers Regional Library - Restrooms - Disability stall doors need to be self-closing. - FS604.8.1.2		FY18	
LIB - 119	Fort Myers Regional Library - Restrooms - FS604.7	Fort Myers Regional Library - Restrooms - All rest rooms have toilet tissue dispensers at 49"-50". - FS604.7		FY18	Discuss with Jill and Kevin: are we obligated onsite to provide the personal devices that are compatible with the website ; can we provide at select locations
LIB - 120	Fort Myers Regional Library - Main Lobby - FS217.1-2-3-4,308.2.1,703.7.2.4,704.2.1,704.4	Fort Myers Regional Library - Main Lobby - Public phone in the lobby. It is at 54", and is not to TTY compliance. - FS217.1-2-3-4,308.2.1,703.7.2.4,704.2.1,704.4		FY18	
LIB - 121	Fort Myers Regional Library - -	Fort Myers Regional Library - - Note: Currently checking on accessibility on Computers. They currently have Zoomtex, which zooms for vision and also audio output. No reader programs for visually impaired or blind. -		FY18	
LIB - 122	Lakes Regional Library - Parking - FS502.6.1	Lakes Regional Library - Parking - Disability parking faded. - FS502.6.1		FY18	
LIB - 123	Lakes Regional Library - Workstations - 28CFR 35.151	Lakes Regional Library - Workstations - Note: Not all workstations, computers need meet Florida Statutes for accessibility, but if they are dispersed throughout the facility, so must a proportionate number meeting the accessibility code. - 28CFR 35.151		FY18	
LIB - 124	Lakes Regional Library - Lobby - FS308	Lakes Regional Library - Lobby - DVD unlocking tool does not meet operable range. - FS308		FY18	
LIB - 125	Lakes Regional Library - Lobby - FS308	Lakes Regional Library - Lobby - Courtesy phone too high. - FS308		FY18	
LIB - 126	Lakes Regional Library - Youth Services - FS308	Lakes Regional Library - Youth Services - Book check-in too high. Accommodation: two self-checkouts are accessible; staff is available to assist - FS308	Year 1= 165,158.53	FY18	FY18 - Update self-checkout equipment
LIB - 127	Lakes Regional Library - Youth Services - FS902.3,306.3	Lakes Regional Library - Youth Services - No disability access for inter-active computer stations; staff is available to assist - FS902.3,306.3		FY18	
LIB - 128	Lakes Regional Library - Youth Services - FS228,309,707.7.1	Lakes Regional Library - Youth Services - Change machine and copies too high. - FS228,309,707.7.1		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 129	Lakes Regional Library - Audio Visual - FS306.3	Lakes Regional Library - Audio Visual - Computer keyboard does not provide minimum knee clearance of 27". - FS306.3		FY18	
LIB - 130	Lakes Regional Library - Audio Visual - FS902.3,308	Lakes Regional Library - Audio Visual - Card catalog computer work station too high with keyboard. - FS902.3,308		FY18	
LIB - 131	Lakes Regional Library - Main floor - FS306.3	Lakes Regional Library - Main floor - Several tables do not provide required knee clearance. - FS306.3		FY18	
LIB - 132	Lakes Regional Library - Main Floor - FS227.3,90.4	Lakes Regional Library - Main Floor - Computer stations for card catalog keyboard too high with no directional signage to accessible stations. - FS227.3,90.4		FY18	
LIB - 133	Lakes Regional Library - Printer Room - FS902.3	Lakes Regional Library - Printer Room - Work surface counters too high. - FS902.3		FY18	
LIB - 134	Lakes Regional Library - Printer Room - FS228,309,707.7.1	Lakes Regional Library - Printer Room - Coin machines too high. - FS228,309,707.7.1		FY18	
LIB - 135	Lakes Regional Library - Printer Room - FS902.3	Lakes Regional Library - Printer Room - Keyboard too high. - FS902.3		FY18	
LIB - 136	Lakes Regional Library - Printer Room - FS228,309,707.7.1	Lakes Regional Library - Printer Room - Copier too high to operate. - FS228,309,707.7.1		FY18	
LIB - 137	Lakes Regional Library - Men's Restrooms - FS606.3	Lakes Regional Library - Men's Restrooms - Main sink 34.5" (H). - FS606.3		FY18	
LIB - 138	Lakes Regional Library - Men's Restrooms - FS604.7	Lakes Regional Library - Men's Restrooms - Toilet paper dispenser to close to grab bar 1.5". - FS604.7		FY18	
LIB - 139	Lakes Regional Library - Youth Services Restrooms - FS0603,604.9	Lakes Regional Library - Youth Services Restrooms - Improper signage for type of restroom (one is suited for adults and one is suited for children). - FS0603,604.9		FY18	
LIB - 140	Lakes Regional Library - Youth Services Restrooms - FS604.9	Lakes Regional Library - Youth Services Restrooms - Right restroom toilet at 19.5" (H), (not child height). - FS604.9		FY18	
LIB - 141	Lakes Regional Library - Youth Services Restrooms - FS308,902.3	Lakes Regional Library - Youth Services Restrooms - Both restrooms baby changing table at 36" (operable handle at 50.5"). - FS308,902.3		FY18	
LIB - 142	Library Admin Office - Entrance - FS403.3	Library Admin Office - Entrance - Access route to front entrance from parking lot exceeds slope. - FS403.3		FY18	
LIB - 143	Library Admin Office - Entrance - FS403.3	Library Admin Office - Entrance - Access sidewalk from parking lot to entrance cross slope exceeds maximum @ 1:48. - FS403.3		FY18	
LIB - 144	Library Admin Office - Entrance -	Library Admin Office - Entrance - Access route to building exceeds slope with no railings. -		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 145	Library Admin Office - Entrance - FS403.5.1	Library Admin Office - Entrance - Front entrance has a pole mounted leaving less than 32" travel clearance. - FS403.5.1		FY18	
LIB - 146	Library Admin Office - Lobby - FS602.7	Library Admin Office - Lobby - Only one water fountain with a height of 36", additional one at 38" minimum. - FS602.7		FY18	
LIB - 147	Library Admin Office - Restrooms - FS604.6	Library Admin Office - Restrooms - Both male & female restrooms toilet handle on wrong side. - FS604.6		FY18	
LIB - 148	Library Admin Office - Restrooms - FS404.2.7,604.8.1.2	Library Admin Office - Restrooms - Accessible stall does not have correct door handle hardware. - FS404.2.7,604.8.1.2		FY18	
LIB - 149	Library Admin Office - Restrooms - FS606.5	Library Admin Office - Restrooms - No under sink protection. - FS606.5		FY18	
LIB - 150	Library Admin Office - Restrooms - FS603.4	Library Admin Office - Restrooms - Hooks exceed reach range of 48". - FS603.4		FY18	
LIB - 151	Northwest Regional - Parking - FS502.6	Northwest Regional - Parking - Several disability parking signs incorrect. - FS502.6		FY18	
LIB - 152	NW Regional Library - Parking - FS502.6	NW Regional Library - Parking - Disability parking spaces missing one sign. - FS502.6		FY18	
LIB - 153	NW Regional Library - -	NW Regional Library - - Note: Not all workstations, computers need meet Florida Statutes for accessibility, but if they are scattered throughout the -		FY18	
LIB - 154	NW Regional Library - Lobby - FS227.3,902.3	NW Regional Library - Lobby - Computer stations for card catalog keyboard too high, 38". - FS227.3,902.3		FY18	
LIB - 155	NW Regional Library - Lobby - FS307.4	NW Regional Library - Lobby - Wall mounted TV protruding out. - FS307.4		FY18	
LIB - 156	NW Regional Library - Lobby - FS228,309,707.3	NW Regional Library - Lobby - East side print station high with approach. - FS228,309,707.3		FY18	
LIB - 157	NW Regional Library - Lobby - FS228,309,707.7.1	NW Regional Library - Lobby - Photo copy and money machine too high to operate. - FS228,309,707.7.1		FY18	
LIB - 158	NW Regional Library - Lobby - FS703.4.2	NW Regional Library - Lobby - "Staff Only" tactile signs X2 wrong location. - FS703.4.2		FY18	
LIB - 159	NW Regional Library - Lobby - FS308.3.1	NW Regional Library - Lobby - Lobby information rack too high to top rack. - FS308.3.1		FY18	
LIB - 160	NW Regional Library - Restrooms - FS603.4	NW Regional Library - Restrooms - Hooks too high. - FS603.4		FY18	
LIB - 168	Pine Island Library - 2 Lobby - FS403.5.1	Pine Island Library - 2 Lobby - Access aisles too narrow in many areas. - FS403.5.1		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 169	Pine Island Library - 2 Lobby - FS902.3	Pine Island Library - 2 Lobby - Entryway card catalog computer incorrect height. - FS902.3		FY18	
LIB - 171	Pine Island Library - 2 Lobby - FS902.3	Pine Island Library - 2 Lobby - Coin operator too high. - FS902.3		FY18	
LIB - 172	Pine Island Library - 2 Lobby - FS902.3	Pine Island Library - 2 Lobby - Printer paper and operator controls too high. - FS902.3		FY18	
LIB - 173	Pine Island Library - 2 Lobby - FS306.3	Pine Island Library - 2 Lobby - Children's section tables too low for knee clearance. - FS306.3		FY18	
LIB - 175	Riverdale Library - Entrance - FS502.1,502.3.1	Riverdale Library - Entrance - Entrance & approach crosshatch too narrow 51". - FS502.1,502.3.1		FY18	
LIB - 176	Riverdale Library - Entrance -	Riverdale Library - Entrance - Entrance/Approach compliant. -		FY18	
LIB - 177	Riverdale Library - Lobby - FS704.2.1,308.3.1,308.3.2	Riverdale Library - Lobby - Public use telephone does not meet accessibility requirements. - FS704.2.1,308.3.1,308.3.2		FY18	
LIB - 178	Riverdale Library - Lobby - FS902.3	Riverdale Library - Lobby - Printer and copy machine too high to for work surface height of 34". - FS902.3		FY18	
LIB - 179	Riverdale Library - Lobby - FS902.3	Riverdale Library - Lobby - Coin operation station too high for work station. - FS902.3		FY18	
LIB - 180	Riverdale Library - Lobby - FS308	Riverdale Library - Lobby - Pamphlet rack near restrooms not within reach range. - FS308		FY18	
LIB - 181	Riverdale Library - Lobby - FS308	Riverdale Library - Lobby - Pamphlet rack near Bios A-Z not within reach range. - FS308		FY18	
LIB - 182	Riverdale Library - Lobby - FS308.3.1	Riverdale Library - Lobby - 4 adult computer tables too low and need to be raised to provide proper knee clearance 27". - FS308.3.1		FY18	
LIB - 183	Riverdale Library - Lobby - FS308.3.1	Riverdale Library - Lobby - 4 Children's computer tables too low and need to be raised to provide proper knee clearance 27". - FS308.3.1		FY18	
LIB - 184	Riverdale Library - Lobby - FS403.5.1	Riverdale Library - Lobby - Horizontal circulation of min. 36" not provided near adult computers. - FS403.5.1		FY18	
LIB - 186	Riverdale Library - Restrooms - FS604.2	Riverdale Library - Restrooms - Uni-sex restroom East water closet too far from wall @ 18.5". - FS604.2		FY18	
LIB - 187	Riverdale Library - Restrooms - FS604.7	Riverdale Library - Restrooms - Uni-sex restroom East toilet paper dispenser too high @ 48.5" - FS604.7		FY18	
LIB - 188	Riverdale Library - Restrooms - FS404.2.4	Riverdale Library - Restrooms - Entry into West family restroom partially blocked by a movable cabinet. - FS404.2.4		FY18	
LIB - 189	Senior Center Lehigh - Entrance - FS404.2.3	Senior Center Lehigh - Entrance - Library exit door incorrect clear width. - FS404.2.3		FY18	

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LIB - 190	Senior Center Lehigh - Entrance - FS404.2.9	Senior Center Lehigh - Entrance - Library exit door pull force too hard. - FS404.2.9		FY18	
LIB - 191	South County Library - Parking - FS502.6	South County Library - Parking - No fines on some disability parking signs. - FS502.6		FY18	
LIB - 192	South County Library - Parking - FS502.3.1	South County Library - Parking - Cross hatch markings are too narrow 4'10". - FS502.3.1		FY18	
LIB - 193	South County Library - Parking - FS502.3	South County Library - Parking - No route of travel from disability parking. - FS502.3		FY18	
LIB - 194	South County Library - Lobby - FS308.2	South County Library - Lobby - General Advisory: Magazine and informational pamphlets racks too high. - FS308.2		FY18	
LIB - 195	South County Library - Lobby - FS305,306,309,902.3,707.3	South County Library - Lobby - No access to copy machine, circular. - FS305,306,309,902.3,707.3		FY18	
LIB - 196	South County Library - Lobby - FS308.2	South County Library - Lobby - Entry "Pay Box" mounted too high. - FS308.2		FY18	
LIB - 197	South County Library - Restrooms - FS703.4.2	South County Library - Restrooms - Restroom directional signage missing disability symbol. - FS703.4.2		FY18	
LIB - 198	South County Library - Restrooms - FS604.5.2	South County Library - Restrooms - All restrooms missing rear grab bar. - FS604.5.2		FY18	
LIB - 199	South County Library - Restrooms - FS604.6	South County Library - Restrooms - Male entry restroom flush handle wrong side. - FS604.6		FY18	
LIB - 200	South County Library - Restrooms - FS604.7	South County Library - Restrooms - Male entry restroom toilet paper dispenser too low. - FS604.7		FY18	
LIB - 201	South County Library - Restrooms - FS603.3	South County Library - Restrooms - Both restrooms mirror too high, 40". - FS603.3		FY18	
LIB - 202	South County Library - Restrooms - FS603.4	South County Library - Restrooms - Both restrooms coat hooks too high. - FS603.4		FY18	
LIB - 203	South County Library - Restrooms	South County Library - Restrooms - Youth service section restrooms are considered not accessible and need signage changed.		FY18	
FAC-					
LTRN	ADA Compliant Bus Stop Improvements & Passenger Amenities	To provide ADA accessible improvements for the passengers. LeeTran is making improvements to bus stop locations to bring them up to the current standards of the Americans with Disabilities Act (ADA).	\$3,025,890		Completion pending final design engineering review
LTRN - 1118	San Carlos Blvd & Summerlin Rd	Phase 15-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0167	Dr Martin Luther King Jr Blvd & Rockfill Rd	Phase 15-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0169	Dr Martin Luther King Jr Blvd & Flint Dr	Phase 15-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LTRN - 0499	Bayshore Rd & Coon Rd	Phase 15-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1576	S Tamiami Trl & Island Park Rd	Phase 15-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0251	S Cleveland Ave & Daniels Pkwy	Phase 15-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1473	S Cleveland Ave & Clayton Ct	Phase 15-7 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1512	Cypress Lake Dr & University Center Blvd	Phase 17-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1540	Cypress Lake Dr & Reflection Lakes Pkwy	Phase 17-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0275	College Pkwy & FSW Pkwy	Phase 17-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0571	Tucker Ln & Hart Dr	Phase 17-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0103	Michigan Ave & Zapato St	Phase 17-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1492	Daniels Pkwy & Danport Blvd	Phase 17-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0560	Mcdaniel Dr & Laurel Ln	Phase 18-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0564	Gish Ln & Ebson Dr	Phase 18-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0589	Pine Island Rd & N Tamiami Tr	Phase 18-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0588	Bayshore Rd & N Tamiami Tr	Phase 18-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0446	Sanibel Blvd & Lee Rd	Phase 18-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0459	Three Oaks Pkwy & Quente Way	Phase 18-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1531	John Morris Rd & Mcgregor Blvd	Phase 19-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1536	Summerlin Rd & Park Royal Dr	Phase 19-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1515	Summerlin Rd & Winkler Rd	Phase 19-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1120	San Carlos Blvd & Linda Loma Dr	Phase 19-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1125	San Carlos Blvd & Kelly Rd	Phase 19-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1113	San Carlos Blvd & Marshwood Ln	Phase 19-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LTRN - 0621	Palm Beach Blvd & Terry Ave	Phase 20-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0652	Palm Beach Blvd & Cartagena Ave	Phase 20-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0913	Joel Blvd & E 6Th St	Phase 20-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 0701	Colonial Blvd & Deer Run Farms Rd	Phase 20-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1831	Winkler Ave & Paissilo Ave	Phase 20-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1830	Winkler Ave & Colonial Blvd	Phase 20-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 2013	Coconut Rd & Via Villagio	Phase 21-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1360	Old 41 & Shangri-La Rd	Phase 21-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1262	Hickory Blvd & Kings Kew	Phase 21-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1244	Hickory Blvd & Kings Kew	Phase 21-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1630	Bonita Beach Rd & Imperial River Rd	Phase 21-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1235	Lovers Key Park & Estero	Phase 21-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$36,135	FY18	Completion pending final design engineering review
LTRN - 1184	San Carlos Blvd & Ft Myers Bch Plaza	Phase 24-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1321	San Carlos Blvd & San Carlos Rv Park	Phase 24-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1181	San Carlos Blvd & Siesta Dr	Phase 24-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1527	Summerlin Rd & John Morris Rd	Phase 24-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1533	Summerlin Rd & M St	Phase 24-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1524	Summerlin Rd & Kelly Cove Dr	Phase 24-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1644	Summerlin Rd & San Carlos Blvd	Phase 25-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1522	Summerlin Rd & Safety St	Phase 25-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1117	San Carlos Blvd & Cinnamon Cove Blvd	Phase 25-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1112	San Carlos Blvd & Mcgregor Blvd	Phase 25-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LTRN - 1781	Gladiolus Dr & San Carlos Blvd	Phase 25-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1780	Gladiolus Dr & San Carlos Blvd	Phase 25-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1519	Summerlin Rd & Bass Rd	Phase 26-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1516	Summerlin Rd & Park Royal Dr	Phase 26-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1139	Winkler Rd & Brindle Ln	Phase 26-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1099	Winkler Rd & Villmoor Ln	Phase 26-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1098	Winkler Rd & Popham Dr	Phase 26-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1097	Winkler Rd & Kimberly Ter	Phase 26-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1142	Winkler Rd & Franchi Blvd	Phase 27-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1095	Winkler Rd & Edgewater Cir	Phase 27-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1094	Winkler Rd & Myerlee Country Club Blvd	Phase 27-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1144	Winkler Rd & Myerlee Country Club Blvd	Phase 27-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1145	Winkler Rd & Lueck Ln	Phase 27-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1093	Winkler Rd & Lueck Ln	Phase 27-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1146	Winkler Rd & Memoli Ln	Phase 28-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1147	Winkler Rd & Cypress Lake Dr	Phase 28-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1091	Cypress Lake Dr & Broadhurst Loop	Phase 28-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1090	Cypress Lake Dr & Overlook Dr	Phase 28-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1511	Cypress Lake Dr & Lake Breeze Dr	Phase 28-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1089	Fsw Ln & Cypress Lake Dr	Phase 28-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1543	Daniels Pkwy & Pine Villa Ln	Phase 29-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1547	Daniels Pkwy & Brookshire Lake Blvd	Phase 29-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LTRN - 1498	Daniels Pkwy & Cross Creek Blvd	Phase 29-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1500	Daniels Pkwy & Six Mile Cypress Pkwy	Phase 29-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1553	Daniels Pkwy & Skyport Ave	Phase 29-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1496	Daniels Pkwy & Shire Ln	Phase 29-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1494	Daniels Pkwy & Palomino Ln	Phase 29-7 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1156	Mason Corbin Ct & Red Cedar Dr	Phase 30-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1601	S Cleveland Ave & D St	Phase 30-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1065	Royal Palm Square Blvd & Summerlin Rd	Phase 30-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1165	Royal Palm Square Blvd & Via Royale	Phase 30-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1164	Royal Palm Square Blvd & Rarco Blv	Phase 30-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1163	Royal Palm Square Blvd & Summerlin Rd	Phase 30-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1064	Via Royale & Royal Palm Square Blvd	Phase 30-7 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1166	Via Royale & Colonial Blvd Ramp	Phase 30-8 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1608	Cleveland Ave & Hill Ave	Phase 31-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1463	Cleveland Ave & Grace Ave	Phase 31-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1460	Cleveland Ave & Hanson St	Phase 31-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1613	Cleveland Ave & Hanson St	Phase 31-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1459	Cleveland Ave & Linhart Ave	Phase 31-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1617	Cleveland Ave & Edison Ave	Phase 31-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1618	Cleveland Ave & Lafayette St	Phase 31-7 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0695	Monroe St & Second St	Phase 31-8 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0747	Orange Grove Blvd & Inlet Dr	Phase 32-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LTRN - 0790	Orange Grove Blvd & Inlet Dr	Phase 32-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0787	Orange Grove Blvd & St Clair Ave W	Phase 32-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0750	Orange Grove Blvd & Golf Club Dr	Phase 32-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0786	Orange Grove Blvd & Golf Club Dr	Phase 32-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0785	Orange Grove Blvd & Riveter Rd	Phase 32-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0797	Se 24Th Ave & Hancock Bridge Pkwy	Phase 33-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 2237	Hancock Bridge Pkwy & Se 16Th Pl	Phase 33-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0741	Se 24Th Ave & Hancock Bridge Pkwy	Phase 33-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0738	Hancock Bridge Pkwy & Se 20Th Ct	Phase 33-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0801	Hancock Bridge Pkwy & Ne 17Th Pl	Phase 33-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0739	Hancock Bridge Pkwy & Ne 22Nd Ave	Phase 33-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1846	Ne 6Th St & Del Prado Blvd S	Phase 34-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0300	Del Prado Blvd N & Ne 6Th Ter	Phase 34-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0387	Del Prado Blvd N & Ne 7Th St	Phase 34-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0778	August St & Orange Grove Blvd	Phase 34-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 2172	Pondella Rd & Ne 25Th Ave	Phase 34-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0545	Pondella Rd & Westwood Dr	Phase 34-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1968	Ne Pine Island Rd & Del Pine Dr	Phase 34-7 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0609	N Cleveland Ave & Pondella Rd	Phase 35-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0762	Pondella Rd & Travis Ave	Phase 35-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0761	Pondella Rd & Green Ave	Phase 35-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0759	Pondella Rd & June Pkwy	Phase 35-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LTRN - 0775	Pondella Rd & June Pkwy	Phase 35-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0770	Pondella Rd & Palm Ave	Phase 35-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0471	N Tamiami Trl & Brooks Rd	Phase 36-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0472	N Tamiami Trl & Crescent Lake Dr	Phase 36-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0476	West Mariana & N Cleveland Ave	Phase 36-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0475	West Mariana & Many Rd	Phase 36-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0478	Merchants Crossing & N Tamiami Trl	Phase 36-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1848	Va Hospital & Va Hospital	Phase 36-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0581	Hart Rd & Forest Park Dr	Phase 37-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0580	Hart Rd & Zoysia Ln	Phase 37-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1883	N Cleveland Ave & Saturn Cir	Phase 37-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0557	Laurel Dr & Garden St	Phase 37-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0550	N Cleveland Ave & Leesure Ln	Phase 37-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0573	Hart Rd & Case Ln	Phase 37-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0566	Ebson Dr & Payne Ln	Phase 37-7 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0495	Bayshore Rd & Hart Rd	Phase 38-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0504	Bayshore Rd & Hart Rd	Phase 38-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0582	Hart Rd & Conestoga Trl	Phase 38-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0496	Bayshore Rd & Whaleys Dr	Phase 38-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0503	Bayshore Rd & Shoreline Blvd	Phase 38-5 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 0499	Bayshore Rd & Coon Rd	Phase 38-6 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1284	Esteros Blvd & Mound Rd	Phase 39-1 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review

ID	Project Name	Project Description	Estimated \$	FY Budget	Status
LTRN - 1305	Estero Blvd & Bayland Rd	Phase 39-2 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1207	Estero Blvd & Donora Blvd	Phase 39-3 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
LTRN - 1206	Estero Blvd & Red Coconut Rv-P	Phase 39-4 - ADA Compliant Bus Stop Improvements & Passenger Amenities	\$15,495	FY19	Completion pending final design engineering review
FAC-MOTI	Museum of the Islands - internal	Tenant is doing interior upgrades	Unknown	FY19	Under way