| ld       | Request Type                           | Description   | Address  | Date Created        | 21926 - Select from the dropdown list of exceptions:                    | 21925 - Tag Number |
|----------|--|---|--|---------------------|---|--------------------|
| 13201686 | Hauler Exceptions List - Hauler Area 1 |   | 415 Washington Ct, Fort Myers Beach, FL, USA           | 2023-01-26 11:52:44 | Loose branches/limbs not compliant                                      | 159258             |
| 13201749 | Hauler Exceptions List - Hauler Area 1 |   | 455 Donora Boulevard, Fort Myers Beach, FL,<br>USA     | 2023-01-26 12:00:49 | Loose branches/limbs not compliant                                      | 159260             |
| 13201752 | Hauler Exceptions List - Hauler Area 1 |   | 27225 Galleon Drive, Bonita Springs, FL, USA           | 2023-01-26 12:01:33 | Loose branches/limbs not compliant                                      | 159266             |
| 13202271 |  | Route F421 MSW unable to service road service truck<br>blocking road  | 3936 Aloha Ln, Bonita Springs, FL, USA                 | 2023-01-26 13:09:55 | Other   |                    |
| 13206017 |  | Customer has 2 toters full of broken tiles, toters are to<br>heavy to lift, cust also has a large loose pile of o& d debris<br>on side, needs to be contained for removal, driver has<br>tagged 2x and cust has not corrected. Resident is out of<br>State, driver has tried to talk to customer. | 21551 Indian Bayou Drive, Fort Myers Beach,<br>FL, USA | 2023-01-27 10:35:44 | Containers/bags over 50 pounds,Construction debris in excess of 2 yards | 160489             |
| 13207011 |  | Very large pile of mixed debris including multiple propane tanks  | 28196 Mango Drive, Bonita Springs, FL, USA             | 2023-01-27 13:13:19 | Construction debris in excess of 2 yards, Materials are hazardous       | 160472             |
| 13207019 | Hauler Exceptions List - Hauler Area 1 |   | 28220 Winthrop Circle, Bonita Springs, FL, USA         | 2023-01-27 13:14:25 | Construction debris in excess of 2 yards                                | 159136             |
| 13207056 |  | driver reports lots of broken glass on the ground around<br>cans and very large solid piece of glass from a table<br>leaning on cans- driver wasn't able to service the cans.<br>Glass was too large to safely put in Rear load truck.  | 3560 Brink Circle, Bonita Springs, FL, USA             | 2023-01-27 13:18:05 | Materials are hazardous   | 159135             |
| 13207145 | Hauler Exceptions List - Hauler Area 1 |   | 27407 Imperial Oak Circle, Bonita Springs, FL,<br>USA  | 2023-01-27 13:28:24 | Loose branches/limbs not compliant                                      | 159253             |
| 13207152 | Hauler Exceptions List - Hauler Area 1 |   | 243 Miramar Street, Fort Myers Beach, FL, USA          | 2023-01-27 13:30:08 | Containers/bags over 50 pounds  | 160530             |
| 13210106 |  | Customer puts loose cat liter in msw toter and pours<br>muriatic acid on material   | 25526 Luci Drive, Bonita Springs, FL, USA              | 2023-01-28 12:39:20 | Materials are hazardous   | 159139             |